

# SD1 – Construction Sequence



# SD1 – Construction Sequence



# SD1 – Construction Sequence





# SD1 – LLDPE Liner Installation (1.5 mm, textured both sides)



# SD1 – LLDPE Liner Deployment





# SD1 – LLDPE Liner Seaming



# SD1 – Placement of Liner Cover





# SD1 – Stage 1 Completed





# SD1 2010 CONSTRUCTION PHOTOS



**AGNICO EAGLE**

# Initial Conditions – Stage 1 completed in 2009 Prior to 2010 Construction






# Foundation Preparation





# Foundation Preparation

## North Abutment





# Rockfill Placement



# Till Placement at Upstream Toe





# Upstream Filter Placement





# Upstream Filter Placement

