



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 2012-10-01	REPORT TIME 18:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 2012-10-01	OCCURRENCE TIME 7:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWA-2AM-MEA0815			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 34		LONGITUDE DEGREES 96 MINUTES 04 SECONDS 18		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO-EAGLE MINES	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED SEWAGE WASTE	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES APP. 8 CUBIC METERS	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE SEWAGE TANK	SPILL CAUSE OVERFLOW	AREA OF CONTAMINATION IN SQUARE METRES 25		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS When operator got to Sewage Treatment Plant, red light alarm for high level in main tank was flashing outside building. He went to check tank outside. It was overflowing from the top. At that time both pumps were on and showing no flow. After verification, effluent pipe was obstructed, explaining why no water was being pumped from the main tank and overflow. Spill was contained in the tank area. Contaminated soil will be removed and disposed of at our tailings storage facility (TSF – authorized by water license). Removal of material is made difficult by the presence of pipes, electrical cable and shack over affected area. There were no off site impact or discharge to any receiving watercourse.				
L	REPORTED TO SPILL LINE BY Robin Allard	POSITION Environment Sr Tech	EMPLOYER Agnico-Eagle Mines	LOCATION CALLING FROM Meadowbank	TELEPHONE 8677634610
M	ANY ALTERNATE CONTACT Kevin Buck	POSITION Environment Superint.	EMPLOYER Agnico-Eagle Mines	ALTERNATE CONTACT Meadowbank LOCATION	ALTERNATE TELEPHONE 8677634610
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					