



## July 15th Spill

Please find that following information that is follow up to the Spill report submitted July 16, 2014 by Agnico Eagle Meadowbank division.

Follow-up:

GPS Coordinates: 65°01'114"W 96°07'124"N.

Photos:

Spill:



During Clean up:



Spill area mixed with rock material to absorb



Berm put in place to stop further



After clean up complete:



If you have any other questions please feel free to contact me at your convenience.

Thank you,

Jeff

**Jeffrey Pratt**  
**Environmental Coordinator**  
**ICMC Facilitator**

[jeffrey.pratt@agnicoeagle.com](mailto:jeffrey.pratt@agnicoeagle.com)

T: 819.759.3555 x6728  
M: 306.960.2370

Agnico Eagle Mines Limited  
Meadowbank Division  
Baker Lake, Nunavut, Canada  
X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)



**AGNICO EAGLE**

