

August 12th, 2014 Spill

Please find the following photos before and after clean-up as a follow up to the Spill report submitted August 12th, 2014 by Agnico Eagle Meadowbank division. All the contaminated material was clean-up and disposed appropriately in the contaminated soil container.

Photos:

Before Clean-up



After Clean-up



If you have any other questions please feel free to contact me at your convenience.

Regards,

Marie-Pier Marcil

Sr. Compliance Technician

marie-pier.marcil@agnicoeagle.com

T: 819.759.3700 x5193

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com



AGNICO EAGLE

