

Remediation

The contaminated area was collected using a backhoe. An estimated volume of 8 cubic meter of contaminated material was collected and brought to the landfarm area. The inside of the c-can was cleaned using absorbent pads. Contaminated pads were disposed of at the HAZMAT area.



Prevention

Procedure for handling and use of zoom-boom was reviewed by warehouse crew. Emphasis was also put on Supervision Formula used on site, specially the inspection phase.



Robin Allard
Environmental - Acting Coordinator
robin.allard@agnicoeagle.com

T: 819.759.3555 x6747

Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0

agnicoeagle.com

