



NWB Tools

Ida Porter &lt;ida.porter@nwb-oen.ca&gt;

---

## **\*\*Follow-up\*\* Reportable Spill at Meadowbank - December 18th, 2015 (Laydown)**

---

**Robin Allard** <robin.allard@agnicoeagle.com>

Tue, Dec 22, 2015 at 8:01 PM

To: Alain Chouinard <achouinard@gov.nu.ca>, "spills@gov.nt.ca" <spills@gov.nt.ca>, "licensing@nunavutwaterboard.org" <licensing@nunavutwaterboard.org>, "rtoolooktook@gov.nu.ca" <rtoolooktook@gov.nu.ca>, "Christine.Wilson@aandc-aadnc.gc.ca" <Christine.Wilson@aandc-aadnc.gc.ca>, "Justin Hack (Justin.Hack@aandc-aadnc.gc.ca)" <Justin.Hack@aandc-aadnc.gc.ca>, Luis Manzo <dirlands@kivalliqinuit.ca>, Jeff Tulugak <jtulugak@kivalliqinuit.ca>, "Jeff Hart (landsbaker@kivalliqinuit.ca)" <landsbaker@kivalliqinuit.ca>, "Harmer, Rob" <RHarmer@gov.nu.ca>

Cc: Meadowbank Environment <meadowbank.environment@agnicoeagle.com>, Kevin Buck <kevin.buck@agnicoeagle.com>, Jason Allaire <jason.allaire@agnicoeagle.com>, Bertin Paradis <bertin.paradis@agnicoeagle.com>, Dominique Girard <dominique.girard@agnicoeagle.com>

Good evening,

Please find the attached information as a follow up to the Spill report submitted December 18<sup>th</sup>, 2015 by Agnico Eagle Meadowbank division.

This detailed report is submitted to the Inspectors in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

If you require further information or have questions, please do not hesitate to contact the undersigned.

**Robin Allard**  
**Environmental - Acting Coordinator**

[robin.allard@agnicoeagle.com](mailto:robin.allard@agnicoeagle.com)

T: 819.759.3555 x6744

Agnico Eagle Mines Limited  
Meadowbank Division  
Baker Lake, Nunavut, Canada  
X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)

**AGNICO EAGLE**

---

**From:** Robin Allard

**Sent:** Friday, December 18, 2015 9:09 PM

**To:** 'Alain Chouinard'; 'spills@gov.nt.ca'; 'licensing@nunavutwaterboard.org'; 'rtoolooktook@gov.nu.ca'; 'Christine.Wilson@aandc-aadnc.gc.ca'; 'Justin Hack (Justin.Hack@aandc-aadnc.gc.ca)'; 'Luis Manzo'; 'Jeff Tulugak'; 'Jeff Hart (landsbaker@kivalliqinuit.ca)'; 'Harmer, Rob'

**Cc:** Meadowbank Environment; Kevin Buck; Jason Allaire; Bertin Paradis; Dominique Girard; Michel Fortin

**Subject:** Reportable Spill at Meadowbank - December 18th, 2015 (Laydown)

Good day,

Attached is a spill report depicting an second incident which took place on December 18<sup>th</sup>, 2015 at Agnico Eagle Mines Ltd., Meadowbank Project.

This spill is being reported as required by the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, item 8 (b) pursuant to subsection 12(3) of the Nunavut Waters and Nunavut Surface Rights Tribunal Act.

This spill is also being reported as required by the Government of Nunavut's, Environmental Protection Act, paragraph 5.1(a).

A follow up report will be submitted following the cleanup actions.

If you require further information or have questions, please do not hesitate to contact the undersigned.

**Robin Allard**  
**Environmental - Acting Coordinator**

[robin.allard@agnicoeagle.com](mailto:robin.allard@agnicoeagle.com)

T: 819.759.3555 x6744

Agnico Eagle Mines Limited  
Meadowbank Division  
Baker Lake, Nunavut, Canada  
X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)





## 4 attachments



December 18, 2015 Laydown call

Please find the following information as a follow up to the last report dated December 10<sup>th</sup>, 2015 for the 2015-12-18 Laydown call. The information is attached to the report in accordance with the conditions of the report and is for your information only.

### Contingency

When a spill occurs, the first step is to contain the spill. This is done by using the spill kit. The spill kit contains absorbent pads, booms, and other materials to contain the spill. The spill kit is used to contain the spill and prevent it from spreading.



**2015-12-18 Laydown oil spill - Follow up\_Page\_1.jpg**  
91K

### Spill

When a spill occurs, the first step is to contain the spill. This is done by using the spill kit. The spill kit contains absorbent pads, booms, and other materials to contain the spill. The spill kit is used to contain the spill and prevent it from spreading.



**2015-12-18 Laydown oil spill - Follow up\_Page\_2.jpg**  
206K

### Remediation

The contaminated area was cleaned using a vacuum. The vacuum removed all of the oil and the contaminated material was collected and brought to the landfill site. The area of the spill was then cleaned and the area was then cleaned.



### Conclusion

The spill was contained and cleaned. The spill was contained and cleaned. The spill was contained and cleaned.



**2015-12-18 Laydown oil spill - Follow up\_Page\_3.jpg**  
216K



**2015-12-18 Laydown oil spill - Follow up.pdf**  
476K