



Canada

## NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

<b>A</b>	REPORT DATE: MONTH – DAY – YEAR <b>2016-01-25</b>	REPORT TIME <b>21:00</b>	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
<b>B</b>	OCCURRENCE DATE: MONTH – DAY – YEAR <b>2016-01-25</b>	OCCURRENCE TIME <b>10:30</b>		
<b>C</b>	LAND USE PERMIT NUMBER (IF APPLICABLE) <b>KIOL-BL-14</b>	WATER LICENCE NUMBER (IF APPLICABLE) <b>NWB-2AM-MEA-1525</b>		
<b>D</b>	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION <b>MEADOWBANK MINE SITE</b>	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
<b>E</b>	LATITUDE DEGREES <b>65</b> MINUTES <b>2</b> SECONDS <b>14</b>	LONGITUDE DEGREES <b>96</b> MINUTES <b>3</b> SECONDS <b>58</b>		
<b>F</b>	RESPONSIBLE PARTY OR VESSEL NAME <b>AGNICO EAGLE MINES LTD</b>	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>BAKER LAKE X0X 0A0</b>		
<b>G</b>	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION		
<b>H</b>	PRODUCT SPILLED <b>ENGINE COOLANT</b>	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>250 LITERS</b>	U.N. NUMBER <b>N/A</b>	
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
<b>I</b>	SPILL SOURCE <b>HAUL TRUCK</b>	SPILL CAUSE <b>BUSTED HOSE</b>	AREA OF CONTAMINATION IN SQUARE METRES <b>500 M2</b>	
<b>J</b>	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	

<b>K</b>	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <b>One of the major coolant hoses had a failure and the coolant system flushed on the ground while going uphill on the Vault hauling road. Truck proceeded to empty load and then stopped so repairs could be safely done. Contaminated material was contained and collected and will be brought to the tailings storage facility.</b>  <b>There were no off site impact or discharge to any receiving watercourses.</b>  <b>Spill location : Northing: 65°04'55" Easting: 95°59'31"</b>  <b>Contact information : Robin Allard 819-759-3555 ext. 6744</b>			
----------	--	--	--	--

<b>L</b>	REPORTED TO SPILL LINE BY <b>ROBIN ALLARD</b>	POSITION <b>COORDINATOR</b>	EMPLOYER <b>Agnico Eagle Mines</b>	LOCATION CALLING FROM <b>MEADOWBANK</b>	TELEPHONE <b>8197593555</b>
<b>M</b>	ANY ALTERNATE CONTACT <b>KEVIN BUCK</b>	POSITION <b>SUPERINTENDENT</b>	EMPLOYER <b>Agnico Eagle Mines</b>	ALTERNATE CONTACT <b>MEADOWBANK</b>	ALTERNATE TELEPHONE <b>8197593555</b>

REPORT LINE USE ONLY					
<b>N</b>	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					