

EQUIPMENT, MATERIALS AND TOOLS

Identify equipment, materials or tools involved in the accident (if any):

Arctic fuel Tanker #96

Condition of equipment, materials or tools:

☒ Compliant ☐ Non-Compliant ☐ N/A

Details (if non-compliant):

Is there an equipment maintenance procedure? ☒ Yes ☐ No ☐ N/A

Date of last preventive maintenance: 2016-03-01

Personal protective equipment involved (boots, hat, eyewear, mask, visor, gloves...):

N/A

Condition of personal protective equipment involved: ☐ Compliant ☐ Non-Compliant ☒ N/A

Details (if non-compliant):

Were they appropriate to the task? ☐ Yes ☐ No ☒ N/A

Details (if non-compliant):

Photo: ☐ Yes ☒ No