

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE TEL: (867) 920-8130

REPORT LINE USE ONLY

TEL: (867) 920-8130 FAX: (867) 873-6924 EMAIL: spills@gov.nt.ca



| Α | REPORT DATE: MONTH – DAY – YEAR 07-04-2016 | | REPC 20:30 | | RT TIME | ORIGINAL SPILL RE | | | | REPO | RT NUMBER - | |
|-----------------------|---|---------------------------------------|---|---|--------------|--|---|-----------------------------------|-----------------|--|---------------------------------|--|
| В | OCCURRENCE DATE: MONTH – DAY – YEAR 07-04-2016 | | | 3:30 | RRENCE TIME | OR | JPDATE : | | EPUKI, | | | |
| С | LAND USE PERMIT NUMBER (IF APPLIC KIOL-BL-14 | • | WATER LICENCE NUI NWB-2AM-MEA-1 | | | MBER (IF APPLICABLE) 525 | | | | | | |
| D | GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FI MEADOWBANK MINE SITE | | | ON FROM THE NAMED LOCATION | | | REGION NT NUNAVUT ADJACENT JURISDICTION | | | | | |
| Ε | LATITUDE DEGREES 65 MINUTES 02 SECONDS | LONGITUDE DEGREES 96 MINUT | | | | ES 03 SECONDS 58 | | | | | | |
| F | RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD | | | RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0 | | | | | | | | |
| G | ANY CONTRACTOR INVOLVED | CONTRACTOR ADDRESS OR OFFICE LOCATION | | | | | | | | | | |
| Н | PRODUCT SPILLED ENGINE OIL 0W30 | | QUANTITY IN LITRES, KILOGRAMS 800 LITERS | | | | | | U.N. NUMBER N/A | | | |
| | SECOND PRODUCT SPILLED (IF APPLICABLE) | | QUANTITY IN LITRES, KILOGRAMS | | | S OR C | UBIC ME | TRES | U.N. NUMBER | | | |
| I | SPILL SOURCE TOTE | | SPILL CAUS PUNCTUR | | | | | AREA OF CONTAMINATION 200 M2 | | | SQUARE METRES | |
| J | FACTORS AFFECTING SPILL OR RECO | DESCRIBE ANY ASSISTANCE REQ | | | UIRED | D HAZARDS TO PERSONS, P ENVIRONMENT | | | S, PRO | PERTY OR | | |
| K | ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS In the process of moving totes from a c-can in the laydown area, the operator of the zoom-boom punctured the tote with his forks. The tote was located at the far end of the c-can. Oil leaked onto the surrounding ground and underneath the c-can. The container was moved and the area cleared and the spill contained. Contaminated material will be collected and brought to the Landfarm area. There were no off site impact or discharge to any receiving watercourses. Distance to closest lake is estimated at 350 meters Spill location on IOL: Northing: 65'01'11" Easting: 96'03'98" Contact information: Robin Allard 819-759-3555 ext. 6744 | | | | | | | | | | | |
| L | REPORTED TO SPILL LINE BY ROBIN ALLARD | INATOR | | | | | CATION CALLING FROM EADOWBANK | | | ELEPHONE 197593555 | | |
| М | ANY ALTERNATE CONTACT POSITION ERIKA VOYER SR COORDIN | | NATOR | | MPLOYER ALTI | | ALTERNA LOCATIO | TERNATE CONTACT CATION MEADOWBANK | | NK 86 | LTERNATE TELEPHONE 577934610 | |
| REPOR | PORT LINE USE ONLY | | | | | | | | | | | |
| Z | RECEIVED AT SPILL LINE BY POSITION Station operat | | | | | | LOCATION CALLED Yellowknife, NT | | D | REPORT LINE NUMBER (867) 920-8130 | | |
| LEAD. | AGENCY EC CCG/TCMSS GNWT AANDC NEB OTHER: | | GN S | | UNKNOWN | | | MAJOR | FILE STATE | | 'US □ OPEN □ CLOSED | |
| AGEN | SENCY CONTACT NAME | | | CONTACT TIME | | | REMARKS | | | | | |
| LEAD AGENCY | | | | | | | | | | | | |
| FIRST SUPPORT AGENCY | | | | | | | | | | | | |
| SECOND SUPPORT AGENCY | | | | | | | | | | | | |
| THIRD SUPPORT AGENCY | | | | | | T | | | | | | |