EQUIPMENT, MATERIALS AND TOOLS	
Identify equipment, materials or tools involved in the accident AFS TRK #20 and trailer #25, 2 c-cans of Nitrate	(if any):
Condition of equipment, materials or tools:	
☐ Compliant ☐ N/A	
Details (if non-compliant): Brake stroke on all axles equipped with maxi chambers showing stroke in excess of 2 inches (measure at the scene) Driver notice that the brakes were all locked-up (but when we checked on site all the wheels were turning while the brakes were applied, see videos)	
Is there an equipment maintenance procedure? ☑ Yes	□ No □ N/A
Date of last preventive maintenance:	
Personal protective equipment involved (boots, hat, eyewear, mask, visor, gloves): Driver had the seat belt on	
Condition of personal protective equipment involved: 区or	mpliant Non-Compliant N/A
Details (if non-compliant):	
Were they appropriate to the task? ☑ Yes ☐ No	□ N/A
Details (if non-compliant):	
	Photo: TVos TNo