

# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

<b>A</b>	REPORT DATE: MONTH – DAY – YEAR 10-23-2016		REPORT TIME 20:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE #	REPORT NUMBER -
<b>B</b>	OCCURRENCE DATE: MONTH – DAY – YEAR 10-23-2016		OCCURRENCE TIME 14:00		
<b>C</b>	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14		WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA-1525		
<b>D</b>	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION MEADOWBANK MINE SITE			REGION <input type="checkbox"/> NT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION	
<b>E</b>	LATITUDE DEGREES 65 MINUTES 02 SECONDS 14		LONGITUDE DEGREES 96 MINUTES 03 SECONDS 58		
<b>F</b>	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
<b>G</b>	ANY CONTRACTOR INVOLVED ARCTIC FUEL	CONTRACTOR ADDRESS OR OFFICE LOCATION BAKER LAKE			
<b>H</b>	PRODUCT SPILLED DIESEL FUEL	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 300 LITERS	U.N. NUMBER 1202		
	SECOND PRODUCT SPILLED (IF APPLICABLE) AMMONIUM NITRATE	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 150 KG	U.N. NUMBER 1942		
<b>I</b>	SPILL SOURCE TRACTOR/CONTAINER	SPILL CAUSE TRACTOR OFF-ROAD	AREA OF CONTAMINATION IN SQUARE METRES 100 M2		
<b>J</b>	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT		
<b>K</b>	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS Hauling containers from the Baker Lake laydown area to the Meadowbank site, a tractor-trailer went uphill at km 102 of the AWAR, apparently could not engage shifting gear and started moving backwards, as it did not have enough momentum to go up the hill. The tractor slid and rolled over off the side of the road. The operator was uninjured and was taken out of the equipment. Diesel fuel was spilling from the truck tanks. The containers, filled with Ammonium Nitrate 1000 kg bags, were damaged in the incident and some product leaked outside by an opening. Products (diesel and nitrate) were never in contact. Spills are contained and stopped and cleanup operations will begin as soon as possible. There were no off site impact or discharge to any receiving watercourses. Distance to closest lake is estimated at 750 meters. Spill location on IOL : Exact GPS location will be provided. Contact information : Robin Allard 819-759-3555 ext. 6744				
<b>L</b>	REPORTED TO SPILL LINE BY ROBIN ALLARD	POSITION ENV COORDINATOR	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197593555
<b>M</b>	ANY ALTERNATE CONTACT ERIKA VOYER	POSITION SR COORDINATOR	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION MEADOWBANK	ALTERNATE TELEPHONE 8677934610
REPORT LINE USE ONLY					
<b>N</b>	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> AANDC <input type="checkbox"/> NEB <input type="checkbox"/> OTHER: _____			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					