

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 11-28-2016		REPORT TIME 21:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE #	REPORT NUMBER -
B	OCCURRENCE DATE: MONTH – DAY – YEAR 11-28-2016		OCCURRENCE TIME 7:30		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14		WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA-1525		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION MEADOWBANK MINE SITE			REGION <input type="checkbox"/> NT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION	
E	LATITUDE DEGREES 65 MINUTES 02 SECONDS 14		LONGITUDE DEGREES 96 MINUTES 03 SECONDS 58		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0		
G	ANY CONTRACTOR INVOLVED ARCTIC FUEL		CONTRACTOR ADDRESS OR OFFICE LOCATION BAKER LAKE		
H	PRODUCT SPILLED ANTIFREEZE		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES TO BE DETERMINED	U.N. NUMBER N/A	
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE TRACTOR		SPILL CAUSE TRACTOR OFF-ROAD	AREA OF CONTAMINATION IN SQUARE METRES 50 M2	
J	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS Hauling containers (2) from the Baker Lake laydown area to the Meadowbank site, a tractor-trailer rolled-over taking a curve at km 65. Upon first assessment the driver mentioned that the load (containers) shifted during the turn causing the trailer to lift, bringing the tractor and trailer to roll-off on the side of the road. The operator was uninjured and was taken out of the equipment. The containers, filled with Ammonium Nitrate 1000 kg bags, appear undamaged in the incident. Antifreeze from the tractor was spilled on the ground, quantity will be determined upon removal of equipment. Recovery operations will begin as soon as possible. There were no off site impact or discharge to any receiving watercourses. Distance to closest lake is estimated at 3,4 kilometers. Spill location : northing 64'47'37" easting 96'20'21". Contact information : Robin Allard 819-759-3555 ext. 6744				
L	REPORTED TO SPILL LINE BY ROBIN ALLARD	POSITION ENV COORDINATOR	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197593555
M	ANY ALTERNATE CONTACT ERIKA VOYER	POSITION SR COORDINATOR	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION MEADOWBANK	ALTERNATE TELEPHONE 8677934610
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> AANDC <input type="checkbox"/> NEB <input type="checkbox"/> OTHER: _____			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY	CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					