

## EQUIPMENT, MATERIALS AND TOOLS

Identify equipment, materials or tools involved in the accident (if any):

Arctic Fuel truck #89 / Trailer #36 and 2 Nitrates sea cans

Condition of equipment, materials or tools:

☐ Compliant ☒ Non-Compliant ☐ N/A

Details (if non-compliant):

AEM Maintenance General Supervisor went to do an inspection on the truck and trailer after the incident.

- First axle on the trailer #36 had a major structural failure on the right side.

Is there an equipment maintenance procedure? ☒ Yes ☐ No ☐ N/A

Date of last preventive maintenance:

Last inspection and work order done October 28, 2016 on the truck#89 / trailer #36.

Personal protective equipment involved (boots, hat, eyewear, mask, visor, gloves...):

N/A

Condition of personal protective equipment involved: ☐ Compliant ☐ Non-Compliant ☒ N/A

Details (if non-compliant):

Were they appropriate to the task?

☐ Yes ☐ No ☒ N/A

Details (if non-compliant):

Photo: ☒ Yes ☐ No