



DANGEROUS OCCURRENCE POSTER

Incident Description: a Dangerous Occurrence occurred on 28 November-2016 -
On the morning of November 28, 2016– an Artic Fuel tractor # 89 and trailer # 36
transporting 2 Nitrate sea-cans fell on the passenger side of unit while in the curve at
km 65– No Spill of product -driver sent to clinic for full precautionary assessment only.

Contributing Factors:


- The first axle on the trailer had a major structural failure on the right side. The trailer was only supporting the load on the right side by the rear two axles.
- Heavy load 44,600 kg. Load capacity of the trailer #36 is 54,000 kg.
- The suspension arm has been welded couple time in the past.

Prevention:

- Random inspections of AFS equipment will be performed to insure adequate maintenance of their fleet.
- An official communication will be sent to AFS to that effect. For the first 3 months, a weekly random inspection will be done; following compliance to good maintenance results, we will move to a monthly random inspection.

Discussion Point: Use the Supervision Formula principle – Inspect, Plan, Decide and Execute before doing any job / task.

Remember: You are the Person Most Responsible for Your Safety!!!



“If the job cannot be done safely, then it cannot be done at Meadowbank”

Working Together for an Accident-Free Workplace

“No Repeats” – Our Stepping Stone to ZERO HARM

2016