

# NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

<b>A</b>	REPORT DATE: MONTH – DAY – YEAR 12-23-2016		REPORT TIME 20:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE #	REPORT NUMBER -
<b>B</b>	OCCURRENCE DATE: MONTH – DAY – YEAR 12-23-2016		OCCURRENCE TIME 16:00		
<b>C</b>	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14		WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA-1525		
<b>D</b>	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM THE NAMED LOCATION MEADOWBANK MINE SITE			REGION <input type="checkbox"/> NT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION	
<b>E</b>	LATITUDE DEGREES 65 MINUTES 02 SECONDS 14		LONGITUDE DEGREES 96 MINUTES 03 SECONDS 58		
<b>F</b>	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0		
<b>G</b>	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION		
<b>H</b>	PRODUCT SPILLED TRANSMISSION OIL		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 340 LITERS	U.N. NUMBER N/A	
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
<b>I</b>	SPILL SOURCE LOADER		SPILL CAUSE BROKEN TRANSMISSION	AREA OF CONTAMINATION IN SQUARE METRES 100 M2	
<b>J</b>	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT	
<b>K</b>	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS During operations at Pit A, the transmission on loader 04 failed and caused transmission oil to be spilled on the ground. The operator of the equipment stopped the equipment right away. The oil was spilled on a blast pattern within the ore. There were no off site impact or discharge to any receiving watercourses. Distance to closest lake is estimated at 750 meters.  Spill location : Northing: 65'01'72" Easting: 96'02'91" on IOL.  Contact information : Robin Allard 819-759-3555 ext. 6744				
<b>L</b>	REPORTED TO SPILL LINE BY ROBIN ALLARD	POSITION ENV COORDINATOR	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197593555
<b>M</b>	ANY ALTERNATE CONTACT ERIKA VOYER	POSITION SR COORDINATOR	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION MEADOWBANK	ALTERNATE TELEPHONE 8677934610
REPORT LINE USE ONLY					
<b>N</b>	RECEIVED AT SPILL LINE BY	POSITION Station operator	EMPLOYER	LOCATION CALLED Yellowknife, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG/TCMSS <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> AANDC <input type="checkbox"/> NEB <input type="checkbox"/> OTHER: _____			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					