



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 05-14-2017	REPORT TIME 7:15pm (CT)	<input type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 05-14-2017	OCCURRENCE TIME 3:00pm (CT)		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA-1525		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 44		LONGITUDE DEGREES 96 MINUTES 02 SECONDS 55	
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0C 0A0		
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED Hydraulic oil	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 80 L	U.N. NUMBER N/A	
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE Excavator BAC 8	SPILL CAUSE Broken Hydraulic Hose	AREA OF CONTAMINATION IN SQUARE METRES 200 m2	
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	

K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS The excavator BAC 8 was cleaning the snow within the East diversion ditch in preparation for freshet, close to NP2 Lake. During the work, an hydraulic hose on BAC 8 broke and hydraulic oil was spilled on the ground of the access road beside the ditch. 80L of oil was spilled, affecting an area of approximately 10m by 20m. Spill pads were placed on the ground as well as containment to collect the oil from the hose. Contaminated snow and material have started to be excavated and will be placed within the landfarm. Environment staff inspected the area and no oil was spilled on the lake ice. Detailed inspection will be completed after clean-up excavation. Containment boom will be placed on the ice of NP2 Lake shore as a preventive measure. Spill location : N65 02'35.2 W096 03'08.9 Reported by: Erika Voyer, Gen. Supervisor. 819-759-3555 ext.6980			
----------	--	--	--	--

L	REPORTED TO SPILL LINE BY Erika Voyer	POSITION Gen. Supervisor	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197593555
M	ANY ALTERNATE CONTACT Jamie Quesnel	POSITION Superintendent	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT MEADOWBANK	ALTERNATE TELEPHONE 8198560821

REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					