



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 08-10-2019	REPORT TIME 4:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 08-10-2019	OCCURRENCE TIME 21:45			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14		WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA1526		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 02 SECONDS 14		LONGITUDE DEGREES 96 MINUTES 03 SECONDS 58		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED HYDRAULIC OIL	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 150 LITERS	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE BACKHOE	SPILL CAUSE HOSE	AREA OF CONTAMINATION IN SQUARE METRES 15 M3		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS During operations at Pit E, an hydraulic hose on the backhoe hammer failed causing a spill. The equipment was stopped and absorbent pads were put on the ground. Once the fitting was replaced, the backhoe was moved and the absorbent pads were picked up. Contaminated soil was collected and brought to the Landfarm area. There were no off site impacts or discharge to any receiving watercourses. Distance to the closest lake is estimated at 500 meters. Spill location: Northing 65' 00'49.1" Easting 96' 03'08.7" Contact information: Robin Allard 819 759 3555 ext. 4606838				
L	REPORTED TO SPILL LINE BY Robin Allard	POSITION General Supervisor	EMPLOYER Agnico Eagle	LOCATION CALLING FROM Meadowbank	TELEPHONE 819 759 3555
M	ANY ALTERNATE CONTACT Nancy Duquet	POSITION Superintendent	EMPLOYER Agnico Eagle	ALTERNATE CONTACT Meadowbank LOCATION	ALTERNATE TELEPHONE 819 856 4385
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					