



Canada

## NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

<b>A</b>	REPORT DATE: MONTH – DAY – YEAR <b>2019-09-06</b>	REPORT TIME <b>8:00 AM</b>	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
<b>B</b>	OCCURRENCE DATE: MONTH – DAY – YEAR <b>2019-09-05</b>	OCCURRENCE TIME <b>12:00 PM</b>			
<b>C</b>	LAND USE PERMIT NUMBER (IF APPLICABLE) <b>KIOL-BL-14</b>	WATER LICENCE NUMBER (IF APPLICABLE) <b>NWB-2AM-MEA-1526</b>			
<b>D</b>	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION <b>MEADOWBANK MINE SITE</b>		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
<b>E</b>	LATITUDE DEGREES <b>65</b> MINUTES <b>01</b> SECONDS <b>19</b>		LONGITUDE DEGREES <b>96</b> MINUTES <b>03</b> SECONDS <b>13</b>		
<b>F</b>	RESPONSIBLE PARTY OR VESSEL NAME <b>AGNICO EAGLE MINES LTD</b>	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>BAKER LAKE X0X 0A0</b>			
<b>G</b>	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
<b>H</b>	PRODUCT SPILLED <b>SULPHUR PRILLS</b>	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>40 KG</b>	U.N. NUMBER <b>1350</b>		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
<b>I</b>	SPILL SOURCE <b>SEA CONTAINER</b>	SPILL CAUSE <b>HUMAN ERROR</b>	AREA OF CONTAMINATION IN SQUARE METRES <b>2 M2</b>		
<b>J</b>	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
<b>K</b>	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <b>Sea container was delivered with damaged bags of sulphur prills. Workers were trying to salvage bags but as they removed them some pallets and bags scraped some spillage out on the ground at the entrance of the container.</b> <b>There were no off site impacts or discharge to any receiving watercourses. Distance to the closest lake is 220 m.</b> <b>Spill location : Northing: 65'01'10' Easting: 96'04'15" on IOL.</b> <b>Contact information : Martin Archambault 819-759-3555 ext. 4606744</b>				
<b>L</b>	REPORTED TO SPILL LINE BY <b>Martin Archambault</b>	POSITION <b>Sr. Env. Coordinator</b>	EMPLOYER <b>Agnico Eagle Mines</b>	LOCATION CALLING FROM <b>MEADOWBANK</b>	TELEPHONE <b>8197593555</b>
<b>M</b>	ANY ALTERNATE CONTACT <b>Robin Allard</b>	POSITION <b>General Supervisor</b>	EMPLOYER <b>Agnico Eagle Mines</b>	ALTERNATE CONTACT <b>MEADOWBANK</b> LOCATION	ALTERNATE TELEPHONE <b>8198601414</b>
REPORT LINE USE ONLY					
<b>N</b>	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					