



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 2022-10-23	REPORT TIME 6:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 2022-10-23	OCCURRENCE TIME 17:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA1530			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 65 MINUTES 0 SECONDS 57		LONGITUDE DEGREES 96 MINUTES 3 SECONDS 52		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0C 0A0			
G	ANY CONTRACTOR INVOLVED ARCTIC FUEL	CONTRACTOR ADDRESS OR OFFICE LOCATION BAKER LAKE			
H	PRODUCT SPILLED Diesel Fuel	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 250L	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE FUEL TANKER	SPILL CAUSE OVERFILL - Human Error	AREA OF CONTAMINATION IN SQUARE METRES 40m2		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS During operations at Meadowbank, an Arctic Fuel driver was refueling tanker #45 at the Meadowbank Tank farm. The driver went back into the truck during refueling and fuel overflowed out of the air vent. Spill pads were immediately placed on the ground and the contaminated snow and material was scraped up. Approximately 6m3 was collected and brought to the Meadowbank landfarm. There were no off site impacts or discharges to any receiving watercourses. Distance to the closest lake is 400m to Third Portage Lake Spill Location: Northing 65' 0' 57" Easting 96' 3' 52" Contact Information: Tom Thomson 819 759 3555 ext. 4606744				
L	REPORTED TO SPILL LINE BY Tom Thomson	POSITION Env. Coordinator	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM 819 759 3555	TELEPHONE 4606744
M	ANY ALTERNATE CONTACT Alex Lavallee	POSITION Env. Superintendent	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION	ALTERNATE TELEPHONE 819 860 0804
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					