



NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 02-29-2024	REPORT TIME 3:30 PM	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 02-28-2024	OCCURRENCE TIME 3:30 PM			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)	WATER LICENCE NUMBER (IF APPLICABLE) NWB-2BB-MEA1828			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES 65 MINUTES 06 SECONDS 30	LONGITUDE DEGREES 95 MINUTES 57 SECONDS 48			
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0C 0A0			
G	ANY CONTRACTOR INVOLVED ORBIT GARANT	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED Engine Oil	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 1L	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE) Coolant	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES >1L	U.N. NUMBER		
I	SPILL SOURCE Bulldozer	SPILL CAUSE Human Error	AREA OF CONTAMINATION IN SQUARE METRES 1m2		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS During exploration on an unnamed lake, approximately 320m N of Wally Lake, a frost fighter installed to warm-up an engine compartment of a bulldozer that suddenly stopped. While thawing the engine compartment, contaminated snow and ice melted resulting in a spill. Approximately 0.5m3 of contaminated snow and ice was collected and brought to the Meadowbank Tailings Storage Facility. The spill occurred on an unnamed lake at the following location, Spill Location: 65° 06'30.44"N 95°57'48.77"W Contact Information: Rowan Woodall 819 759 3555 ext. 4606744				
L	REPORTED TO SPILL LINE BY Rowan Woodal	POSITION Env. Coordinator	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM Meadowbank	TELEPHONE 819-759-3555
M	ANY ALTERNATE CONTACT Robin Allard	POSITION Env. Gen. Supervisor	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION Meadowbank	ALTERNATE TELEPHONE 819-860-1414
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					