



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 08-02-2024	REPORT TIME 8:45	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 08-01-2024	OCCURRENCE TIME 17:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA1530			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK COMPLEX	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES 64 MINUTES 57 SECONDS 11	LONGITUDE DEGREES 96 MINUTES 11 SECONDS 41			
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0C 0A0			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED DIESEL FUEL / WATER MIXTURE	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 500L	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE HOSE	SPILL CAUSE HUMAN ERROR	AREA OF CONTAMINATION IN SQUARE METRES 24M2		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS While performing water draw from the fuel tank #5 on the JET-A tanks pad at the Baker Lake Marshalling facilities, a worker failed to secure the disconnected hose used during the transfer between the fuel tank and the fuel tanker. The hose slipped from it's upright position to the ground, releasing it's contents by gravity onto the pad. Approximately 500L of a diesel fuel and water mixture leaked out. A loader was immediately brought to remove the contaminated material, which was then transported to the Meadowbank landfarm for disposal. There were no off site impacts or discharges to any receiving watercourse. Distance to the closest lake is 450m to Baker Lake. Spill Location: N 64°18'29.47"N W 95°56'52.60"W on IOL				
L	REPORTED TO SPILL LINE BY Samuel Tapp	POSITION Env. Coordinator	EMPLOYER Agnico Eagle	LOCATION CALLING FROM Meadowbank	TELEPHONE 819-759-3555
M	ANY ALTERNATE CONTACT Eric Haley	POSITION Superintendent	EMPLOYER Agnico Eagle	ALTERNATE CONTACT Meadowbank LOCATION	ALTERNATE TELEPHONE 819-651-1010
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					