



AGNICO EAGLE

MEADOWBANK COMPLEX

Monitoring Program Summary Report

April 2026

Type A Water License 2AM-MEA1530

Table of Contents

- SECTION 1 • BACKGROUND 3**
- SECTION 2 • WATER MANAGEMENT..... 4**
 - 2.1 WATER USAGE4
 - 2.2 WASTE ROCK STORAGE FACILITY SEEPAGE4
 - 2.3 CENTRAL DIKE SEEPAGE.....4
 - 2.4 ASSAY ROAD SEEPAGE.....4
 - 2.5 SEEPAGE AND RUNOFF FROM THE LANDFILL4
 - 2.6 SEWAGE TREATMENT PLANT4
 - 2.7 VAULT ATTENUATION POND EFFLUENT6
 - 2.8 PHASER ATTENUATION POND6
 - 2.9 EAST DIKE SEEPAGE EFFLUENT6
 - 2.10 NON-CONTACT WATER.....6
 - 2.11 IN-PIT DISPOSAL6
- SECTION 3 • SPILL MANAGEMENT 7**
 - 3.1 KM 87 SPILL FOLLOW UP8

SECTION 1 • BACKGROUND

On June 13, 2020, Agnico Eagle received the minister's approval for the Water License 2AM-MEA1530 Amendment No.4. This amendment was required to authorize changes to the previously approved uses of water and deposit of wastes needed to reflect the expansion of the Whale Tail Mine.

As required under Part I, Item 21 of Type A Water License 2AM-MEA1530 (Amendment No.4), this report documents the water management and monitoring activities at the mine site for the month. This includes water usage, Vault Attenuation Pond and Phaser Attenuation Pond discharge, East Dike Seepage discharge water quality, RSF Seepage, Central Dike Seepage, Assay Road Seepage, sewage treatment plant discharge water quality (which is directed to the onsite stormwater management pond), an update to the In-Pit disposal and follow up to the AWAR spill at KM 87.

In addition, a summary of spills/actions for the month is reported.

SECTION 2 • WATER MANAGEMENT

2.1 WATER USAGE

Freshwater usage for the month is summarized in Table 2.1 below.

Table 2.1: Freshwater Usage (m³)

Water Location	Source Lake	Jan	Feb	Mar	Apr	Total
Camp	Third Portage Lake	2,737	2,572	2,734	2,695	10,738
Mill (freshwater tank)	Third Portage Lake	50,779	45,698	46,833	27,401	170,711
Emulsion plant	Unnamed Lake	0	0	0	0	0
Total Freshwater Usage (m³)		53,516	48,270	49,567	30,096	181,449
Ore Water (m³)	Ore	4,660	3,613	3,611	2,957	14,841
Reclaim Water Usage (m³)	Tailings Pond	217,843	198,127	213,719	179,584	809,273

2.2 WASTE ROCK STORAGE FACILITY SEEPAGE

In April, no water was pumped back to Portage Pits from the ST-16 sump. No sampling was completed at ST-16, WEP1 (Station ST-30) or WEP2 (station ST-31) during the month as they were frozen.

Agnico Eagle completed inspections at the Portage and Vault RSFs, no non-conformities were found during the month.

2.3 CENTRAL DIKE SEEPAGE

In April, no sample was taken and no water was pumped from ST-S-5 sump to Portage Pits due to frozen condition.

Visual inspections are completed monthly, by the Environment Department, as well as daily monitoring of piezometric values.

2.4 ASSAY ROAD SEEPAGE

In April, no water was pumped from the mill trench back to the mill due to frozen conditions. Routine inspections occurred during the month.

2.5 SEEPAGE AND RUNOFF FROM THE LANDFILL

The landfill was inspected weekly, and no seepage or runoff was observed.

2.6 SEWAGE TREATMENT PLANT

One (1) effluent wastewater sample was collected at the onsite sewage treatment plant (STP) in April. The Seprotech STP results are shown in Table 2.6.1 below; the LJ-Mix STP results

are shown in Table 2.6.2. The effluent from the STP is discharged to the Stormwater Management Pond.

In April, no water was pumped from the Stormwater Management Pond to Portage Pits.

Table 2.6.1: Seprotech Effluent Results

Parameters	Units	4/6/2026
Unionized Ammonia (NH ₃)	mg N/L	0.51
Ammonia-Nitrogen (NH ₃ -NH ₄)	mg N/L	60
Total Kjeldahl Nitrogen	mg N/L	57
BOD-5	mg/L	9
COD	mg/L	57
Total Suspended Solids	mg/L	10
Nitrate	mg N/L	1.66
Nitrite	mg N/L	1.14
pH*	Units	7.30
Fecal Coliform**	UFC/100 mL	140
Total Coliform**	UFC/100 mL	2,800

*Parameter measured by STP operators

**Results are from April 15th

Table 2.6.2: LJ-Mix Effluent Results

Parameters	Units	4/6/2026
Unionized Ammonia (NH ₃)	mg N/L	0.15
Ammonia-Nitrogen (NH ₃ -NH ₄)	mg N/L	33
Total Kjeldahl Nitrogen	mg N/L	41
BOD-5	mg/L	16
COD	mg/L	80
Total Suspended Solids	mg/L	26
Nitrate	mg N/L	25.9
Nitrite	mg N/L	1.36
pH*	Units	7.06
Fecal Coliform**	UFC/100 mL	2,100
Total Coliform**	UFC/100 mL	15,000

*Parameter measured by STP operators

**Results are from April 15

2.7 VAULT ATTENUATION POND EFFLUENT

No discharge has occurred from the Vault Attenuation Pond to Wally Lake during the month.

2.8 PHASER ATTENUATION POND

No water was pumped from the Phaser Attenuation Pond during the month.

No water was transferred from BB Phaser Pit sumps to the Phaser Attenuation Pond during the month.

2.9 EAST DIKE SEEPAGE EFFLUENT

No water was discharged from the East Dike seepage to Second Portage Lake during the month. In April, water from the East Dike seepage was discharged into Portage Pits.

2.10 NON-CONTACT WATER

Portage Area East diversion ditch (ST-5) and West diversion ditch (ST-6) were not sampled in April due to the diversion ditches being frozen. Sampling is conducted during open water conditions.

2.11 IN-PIT DISPOSAL

Tailings were disposed of in Portage Pits and reclaim water was taken from Portage Pits for the month.

SECTION 3 • SPILL MANAGEMENT

Figure 3.1 shows reported and non-reported spills for 2026 broken down per month, and Table 3.1 summarizes Agnico Eagle spill reports for April.

Four (4) spills occurred on site during the month with one (1) reported to regulators. Spills were contained and cleaned, contaminated material was disposed of in the appropriate area, and the clean-up actions were monitored closely by the Environment Department. There were no off-site impacts to any watercourses.

Figure 3.1 2026 Reported and Non-Reported Spills




Table 3.1: Summary of Agnico Eagle Internal and Reported Spill Reports, April 2026

Date of Spill	Hazardous Material	Quantity	Units	Location	Cause of spill	Clean-up action taken
4/10/2026	Diesel Fuel	90	L	Meadowbank Fuel Farm	Equipment malfunction	Contaminated soil was collected and disposed of at the Meadowbank Landfarm.
4/13/2026	Diesel Fuel	70	L	PEL Shop	Human error	Contaminated soil was collected and disposed of at the Meadowbank Landfarm.
4/15/2026	Hydraulic Oil	150	L	SANA Old Crusher Pad	Human error	Contaminated soil was collected and disposed of at the Meadowbank Landfarm.
4/23/2026	Diesel Fuel	80	L	Meadowbank Fuel Farm	Equipment malfunction	Contaminated soil was collected and disposed of at the Meadowbank Landfarm.

3.1 KM 87 SPILL FOLLOW UP

In April, Agnico Eagle completed inspections at KM87 spill areas. No samples were collected during the month due to frozen conditions.