





Water Licence Inspection Report

Original
 Follow-Up Report

Authorization	Representative
2AM-MEL1631	John Baechler
Authorization No. / Expiry	Representative's Title
March 31, 2031	Environment General Supervisor
Inspection Date	Inspector
March 26, 2026	RMO Kyle Amsel
Other Authorization/s	
Activities Inspected	
<input type="checkbox"/> Municipal <input checked="" type="checkbox"/> Camp, Commercial <input type="checkbox"/> Drilling <input checked="" type="checkbox"/> Mining <input checked="" type="checkbox"/> Construction <input checked="" type="checkbox"/> Reclamation <input checked="" type="checkbox"/> Fuel Storage <input checked="" type="checkbox"/> Roads/Hauling <input type="checkbox"/> Winter Hauling <input type="checkbox"/> Camp, Private <input type="checkbox"/> Other Click or tap here to enter text.	

Section 1 Comments
<p>On March 26, 2026 Resource Management Officer Kyle Amsel (Inspector) for Crown-Indigenous Relations and Northern Affairs Canada conducted an Inspection of Water Licence 2AM-MEL1631 (Licence) issued to Agnico Eagle Mines Ltd. (Proponent) for use of water and deposit of waste in support of a Mining Undertaking (Undertaking).</p> <p>Accompanying the Inspector was John Baechler Environment General Supervisor (Representative).</p> <p>Preliminary Information</p> <p>The purpose of the inspection was to determine compliance with the Licence.</p> <p>Observations</p> <ol style="list-style-type: none"> 1) Work is underway on the CP-8 Thermal berm and CP-8 with CP-8 anticipated to be commissioned on April 8th. These pieces of infrastructure are intended for water management of expanded Tailings Storage Facility. (Photo 1) 2) Berm B7 is completed. (Photo 2) 3) Construction is underway for a shop in the Pump Development area which support works in the area. (Photo 3) 4) At time of Inspection water usage to date was 31,888m³ at MEL-11. Tiriganiaq Pit 1 was being mined and there was no activity at Tiriganiaq 2.
Section 2 Non-Compliance
No instances of non-compliance
Section 3 Action Required
No actions required
Section 4 Other

Licensee or Representative	Inspector's Name
John Baechler	RMO Amsel
Signature	Signature
 Signed only to demonstrate reception	
Date	Date
April 24, 2026	April 17, 2026

Office Use Only: Follow-up report to be issued by Inspector <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No



PHOTO LOG

Date: March 26, 2026	Authorization Number: 2AM-MEL1631	Camera/Model: Nikon Coolpix	Inspector: RMO AMSEL
--------------------------------	---	---------------------------------------	--------------------------------

Photo # 1	Coordinates: N63° 2' 20" W92° 15' 42"
------------------	--



Description:
CP8 under construction (Photo left). Photo taken on top of CP-8 Thermal berm.

Photo # 2	Coordinates: N63° 2' 19" W92° 15' 43"
------------------	--



Description:
Berm B7 completed.



Photo # 3 Coordinates: N63° 1' 13" W92° 13' 46"



Description:
Construction in Pump area.