



Photo 25: Compacted Type A material along North water collection channel alignment
View from Station 4+060 facing up chainage



Photo 26: Placing transition material (150 mm minus) on geotextile along North channel
View from Station 4+180 facing up chainage



Photo 27: Finalizing construction on South collection channel
View from Station 4+200 of North channel



Photo 28: Mucking sump area
View from dike



Photo 29: Completed sump
View facing northeast



Photo 30: Installing HGTC-4 , cable being inserted in 25 mm ID PVC pipe lying on liner between Station 0+420 and 0+470



Photo 31: HGTC-2 is in the 25 mm I.D. PVC pipe shown– terminal out of the key trench downstream side at Station 0+290



Photo 32: Arrows pointing at terminals for HGTC-3 and HGTC-4