



Canada

## NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR <b>June 08-2017</b>		REPORT TIME <b>19:04</b>		<input type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	B	OCCURRENCE DATE: MONTH – DAY – YEAR <b>Unknown</b>		OCCURRENCE TIME <b>Unknown</b>		
C		LAND USE PERMIT NUMBER (IF APPLICABLE) <b>KVCL102J168</b>		WATER LICENCE NUMBER (IF APPLICABLE) <b>2AM-MEL1631</b>		
	D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION <b>MELIADINE GOLD PROJECT</b>			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E		LATITUDE DEGREES <b>63</b> MINUTES <b>1</b> SECONDS <b>24</b>			LONGITUDE DEGREES <b>92</b> MINUTES <b>11</b> SECONDS <b>7</b>	
	F	RESPONSIBLE PARTY OR VESSEL NAME <b>Agnico Eagle Mines Ltd</b>		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>Meliadine, Rankin Inlet, Nunavut, X0C 0G0</b>		
G		ANY CONTRACTOR INVOLVED <b>Orbit Garant</b>		CONTRACTOR ADDRESS OR OFFICE LOCATION <b>3200, boul. Jean-Jacques Cossette, Val d'Or, QC J9P 6Y6</b>		
	H	PRODUCT SPILLED <b>Hydraulic Oil</b>		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>Unknown</b>		U.N. NUMBER
I		SECOND PRODUCT SPILLED (IF APPLICABLE) <b>NA</b>		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>NA</b>		U.N. NUMBER
	J	SPILL SOURCE <b>Hydraulic Oil Hose Drip</b>		SPILL CAUSE <b>Equipment Malfunction</b>		AREA OF CONTAMINATION IN SQUARE METRES <b>NA</b>
K		FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT
	L	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <b>Drilling activities have been underway near Lake B8 and a small drip from a hydraulic hose in the drilling shack was observed when the drill was being demobilized from the location. The hose was dripping for an unknown duration, however, maintenance and a hose change was conducted approximately 3-weeks prior to the spill report. Lake B8 is a non-fish bearing lake. Despite B8 being non-fish bearing lake, it remains a non-contact water body as part of Meliadine's Water Management Plan until the dike D-CP4 is constructed and B8 becomes containment pond CP4. At present moment, the impact to B8 is expected to be minimal; however, ongoing spill clean up and observations are planned as snow and ice thaws at this location (GPS UTM 83 Z015: 539096.07, 6988864.61, 1006.40). The drill will be inspected and repaired prior to starting at the next location and better secondary containment to be sought to reduce risks from hose drips. Spill report by Jennifer Brown 819-759-3555 ext. 3996</b>				
M		REPORTED TO SPILL LINE BY <b>Jennifer Brown</b>	POSITION <b>Sr. Env Coordinator</b>	EMPLOYER <b>Agnico Eagle</b>	LOCATION CALLING FROM <b>Meliadine</b>	TELEPHONE <b>819-759-3555</b>
	N	ANY ALTERNATE CONTACT <b>Jessica Huza</b>	POSITION <b>Gen Supervisor</b>	EMPLOYER <b>Agnico Eagle</b>	ALTERNATE CONTACT <b>Mirabel</b>	ALTERNATE TELEPHONE <b>819-759-3555</b>
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						