



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 06-13-2018		REPORT TIME 11:00		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER 18 - _____
	B	OCCURRENCE DATE: MONTH – DAY – YEAR 6-12-2018		OCCURRENCE TIME 11:00		
C		LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01			WATER LICENCE NUMBER (IF APPLICABLE) 2AM-MEL1631	
	D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E		LATITUDE DEGREES 63 MINUTES 1 SECONDS 43			LONGITUDE DEGREES 92 MINUTES 10 SECONDS 9	
	F	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0		
G		ANY CONTRACTOR INVOLVED None		CONTRACTOR ADDRESS OR OFFICE LOCATION		
	H	PRODUCT SPILLED Sewage		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES ~3000L	U.N. NUMBER	
I		SECOND PRODUCT SPILLED (IF APPLICABLE) None		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER NA	
	J	SPILL SOURCE Retention Tank Lift Station		SPILL CAUSE Ground thaw		AREA OF CONTAMINATION IN SQUARE METRES
K		FACTORS AFFECTING SPILL OR RECOVERY N/A		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT
	L	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS As the ground started to thaw, the building sank into the ground which induced strain on the connection for the discharge line. This resulted in the line disconnecting and when the lift station level reached its preset level started the pumps and the effluent discharged inside the building and eventually leaked onto the ground. Sewage was removed with a hydro suction truck and stored for sewage treatment discharge. Sr. Environmental Coordinator - Jennifer Brown: Ext 3996 Sr. Environmental Technician - Justin MacMillan: Ext 3903 or 3925				
M		REPORTED TO SPILL LINE BY Jennifer Brown	POSITION Sr. Env Coordinator	EMPLOYER Agnico Eagle	LOCATION CALLING FROM Meliadine Project	TELEPHONE 8197593555
	N	ANY ALTERNATE CONTACT Justin MacMillan	POSITION Sr. Env Technician	EMPLOYER Agnico Eagle	ALTERNATE CONTACT Meliadine Project	ALTERNATE TELEPHONE 8197593555
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						