



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 12-15-2020		REPORT TIME 16:45		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	OCCURRENCE DATE: MONTH – DAY – YEAR 12-15-2020		OCCURRENCE TIME 00:30			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01			WATER LICENCE NUMBER (IF APPLICABLE) 2AM-MEL1631		
	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 63 MINUTES 2 SECONDS 4			LONGITUDE DEGREES 92 MINUTES 13 SECONDS 14		
	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0			
G	ANY CONTRACTOR INVOLVED N/A		CONTRACTOR ADDRESS OR OFFICE LOCATION N/A			
	PRODUCT SPILLED Hydraulic Oil		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 280 Liters		U.N. NUMBER	
H	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A		U.N. NUMBER N/A	
	SPILL SOURCE Haul Truck		SPILL CAUSE Broken Hose		AREA OF CONTAMINATION IN SQUARE METRES 6 M2	
J	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS A broken hydraulic hose on a 50T haul truck led to the release of an estimated 280L of hydraulic oil on Ore Pad 2 (OP2). The equipment was stopped and absorbent pads laid out to contain the spill. Clean-up work is underway. No water bodies were impacted by this spill. The nearest natural water-body (B7) is 500 m away. A follow-up report will be issued after a closer investigation is completed. Reported by Sean Arruda Environment Coordinator 819-759-3555 ext. 4603996 sean.arruda@agnicoeagle.com.					
L	REPORTED TO SPILL LINE BY Sean Arruda	POSITION Env. Coordinator	EMPLOYER AEM	LOCATION CALLING FROM Meliadine	TELEPHONE 819-759-3555	
	M	ANY ALTERNATE CONTACT Robin Allard	POSITION Env. Gen. Supervisor	EMPLOYER AEM	ALTERNATE CONTACT Meliadine	ALTERNATE TELEPHONE 819-860-1414
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						