NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE
TEL: (867) 920-8130
FAX: (867) 873-6924
EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR **08-03-2022**	REPORT TIME **18:00**	☐ ORIGINAL SPILL REPORT, OR ☒ UPDATE # **1** TO THE ORIGINAL SPILL REPORT	REPORT NUMBER **20 - 22425**
B	OCCURRENCE DATE: MONTH – DAY – YEAR **08-02-2022**	OCCURRENCE TIME **18:30**		

C	LAND USE PERMIT NUMBER (IF APPLICABLE) **KVPL11D01**	WATER LICENCE NUMBER (IF APPLICABLE) **2AM-MEL1631**
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION **Meliadine Gold Project**	REGION ☐ NWT ☒ NUNAVUT ☐ ADJACENT JURISDICTION OR OCEAN
E	LATITUDE DEGREES **63** MINUTES **2** SECONDS **21**	LONGITUDE DEGREES **92** MINUTES **13** SECONDS **41**
F	RESPONSIBLE PARTY OR VESSEL NAME **Agnico Eagle Mines Ltd.**	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION **Meliadine, Rankin Inlet, Nunavut, X0C 0G0**
G	ANY CONTRACTOR INVOLVED **N/A**	CONTRACTOR ADDRESS OR OFFICE LOCATION **N/A**

H	PRODUCT SPILLED **Untreated sewage**	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES **20 Litres**	U.N. NUMBER **N/A**
	SECOND PRODUCT SPILLED (IF APPLICABLE) **N/A**	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES **N/A**	U.N. NUMBER **N/A**
I	SPILL SOURCE **Wing C Lift Station**	SPILL CAUSE **Equipment malfunction**	AREA OF CONTAMINATION IN SQUARE METRES **1**
J	FACTORS AFFECTING SPILL OR RECOVERY **N/A**	DESCRIBE ANY ASSISTANCE REQUIRED **N/A**	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT **N/A**

K — ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS

An overflow occurred at the wing c lift station resulting in a spill of 20 L of untreated sewage to the industrial pad. The spill was contained to the local area.

The coordinates of the spill are 63º 2’ 23.09’’N, 92º 13’ 32.69’’W. No water bodies were impacted by this spill. The nearest natural water body (G2) is 360 m northwest.

Pursuant to Part H, Item 8c of water license 2AM-MEL1631, a follow up report will be issued after the investigation is completed.

Reported by Randy Schwandt Environment Coordinator 819-759-3555 ext. 4603996
Randy.schwandt@agnicoeagle.com , kyle.conway@agnicoeagle.com ext. 4603212

L	REPORTED TO SPILL LINE BY **Randy Schwandt**	POSITION **Env. Coordinator**	EMPLOYER **AEM**	LOCATION CALLING FROM **Meliadine**	TELEPHONE **819-759-3555**
M	ANY ALTERNATE CONTACT **Kyle Conway**	POSITION **General Supervisor**	EMPLOYER **AEM**	ALTERNATE CONTACT LOCATION **Meliadine**	ALTERNATE TELEPHONE **819-759-3555**

REPORT LINE USE ONLY

N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130

LEAD AGENCY ☐ EC ☐ CCG ☐ GNWT ☐ GN ☐ ILA ☐ INAC ☐ NEB ☐ TC | SIGNIFICANCE ☐ MINOR ☐ MAJOR ☐ UNKNOWN | FILE STATUS ☐ OPEN ☐ CLOSED

AGENCY	CONTACT NAME	CONTACT TIME	REMARKS
LEAD AGENCY			
FIRST SUPPORT AGENCY			
SECOND SUPPORT AGENCY			
THIRD SUPPORT AGENCY			