



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 10-15-2022		REPORT TIME 10:15		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	OCCURRENCE DATE: MONTH – DAY – YEAR 10-15-2022		OCCURRENCE TIME 24:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01			WATER LICENCE NUMBER (IF APPLICABLE) 2AM-MEL1631		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 63 MINUTES 2 SECONDS 21			LONGITUDE DEGREES 92 MINUTES 13 SECONDS 41		
F	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0			
G	ANY CONTRACTOR INVOLVED N/A		CONTRACTOR ADDRESS OR OFFICE LOCATION N/A			
H	PRODUCT SPILLED Hydraulic Oil		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 250 Litres		U.N. NUMBER	
	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER	
I	SPILL SOURCE Hydraulic hose failure		SPILL CAUSE Broken hose		AREA OF CONTAMINATION IN SQUARE METRES 5	
J	FACTORS AFFECTING SPILL OR RECOVERY N/A		DESCRIBE ANY ASSISTANCE REQUIRED N/A		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT N/A	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS A broken hydraulic hose on a haul truck led to the release of an estimated 250 L of hydraulic oil on Ore Pad 1 (OP1). The spill was contained to the local area and clean up is currently ongoing. The coordinates of the spill are 63° 1' 40.15"N, 92° 12' 43.73"W. No water bodies were impacted by this spill. The nearest natural water body (B7) is 900 m west. Pursuant to Part H, Item 8c of water license 2AM-MEL1631, a follow up report will be issued after the investigation is completed. Reported by Randy Schwandt, Environment Coordinator 819-759-3555 ext. 4603996 Randy.Schwandt@agnicoeagle.com , Sara.Savoie@agnicoeagle.com ext. 4603212					
L	REPORTED TO SPILL LINE BY Randy Schwandt	POSITION Env. Coordinator	EMPLOYER AEM	LOCATION CALLING FROM Meliadine	TELEPHONE 819-759-3555	
M	ANY ALTERNATE CONTACT Sara Savoie	POSITION General Supervisor	EMPLOYER AEM	ALTERNATE CONTACT LOCATION Meliadine	ALTERNATE TELEPHONE 819-856-9349	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						