



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 10-18-2022	REPORT TIME 18:00	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 10-18-2022	OCCURRENCE TIME 8:15			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-MEL1631			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 63 MINUTES 2 SECONDS 21		LONGITUDE DEGREES 92 MINUTES 13 SECONDS 41		
F	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0			
G	ANY CONTRACTOR INVOLVED N/A	CONTRACTOR ADDRESS OR OFFICE LOCATION N/A			
H	PRODUCT SPILLED Sewage	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 30 Litres	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Vacuum Truck Hose	SPILL CAUSE Human Error	AREA OF CONTAMINATION IN SQUARE METRES 2		
J	FACTORS AFFECTING SPILL OR RECOVERY N/A	DESCRIBE ANY ASSISTANCE REQUIRED N/A	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT N/A		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS In the process of emptying the sewage treatment plant sludge tank, the transfer line was not drained properly resulting in a 30 L spill of sewage to the industrial pad. The spill was contained to the local area. The coordinates of the spill are 63° 2' 22.92"N, 92° 13' 33.02"W. No water bodies were impacted by this spill. The nearest natural water body (G2) is 370 m northwest. Pursuant to Part H, Item 8c of water license 2AM-MEL1631, a follow up report will be issued after the investigation is completed. Reported by Randy Schwandt, Environment Coordinator 819-759-3555 ext. 4603996 Randy.Schwandt@agnicoeagle.com, Kyle.Conway@agnicoeagle.com ext. 4603212				
L	REPORTED TO SPILL LINE BY Randy Schwandt	POSITION Env. Coordinator	EMPLOYER AEM	LOCATION CALLING FROM Meliadine	TELEPHONE 819-759-3555
M	ANY ALTERNATE CONTACT Kyle Conway	POSITION General Supervisor	EMPLOYER AEM	ALTERNATE CONTACT Meliadine LOCATION	ALTERNATE TELEPHONE 819-860-1033
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					