



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 2023-08-05	REPORT TIME 10:30	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 2023-08-04	OCCURRENCE TIME 18:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-MEL1631			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 63 MINUTES 2 SECONDS 21		LONGITUDE DEGREES 92 MINUTES 13 SECONDS 41		
F	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0			
G	ANY CONTRACTOR INVOLVED N/A	CONTRACTOR ADDRESS OR OFFICE LOCATION N/A			
H	PRODUCT SPILLED Sewage	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 125 Litres	U.N. NUMBER N/A		
	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A	U.N. NUMBER N/A		
I	SPILL SOURCE Wing 8 Lift Station	SPILL CAUSE Equipment Failure	AREA OF CONTAMINATION IN SQUARE METRES 1 m2		
J	FACTORS AFFECTING SPILL OR RECOVERY Infrastructure	DESCRIBE ANY ASSISTANCE REQUIRED N/A	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT N/A		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS An overflow of the Wing 8 Lift Station resulted in a spill of 125 L of sewage to the industrial pad. The spill was contained to the local area. Clean up activities were immediately undertaken. The coordinates of the spill are 63° 2'23.38" N, 92°13'48.34" W . No water bodies were impacted by this spill. The nearest natural water body (G2) is located 208 m northwest. Pursuant to Part H, Item 8c of the 2AM-MEL1631 Water Licence, a follow-up report will be issued after the investigation is completed. Reported by Matt Gillman, Environment Superintendent 819-759-3555 ext. 4603175 matt.gillman@agnicoeagle.com, alternate contact: sara.savoie@agnicoeagle.com ext. 4603212				
L	REPORTED TO SPILL LINE BY Matt Gillman	POSITION Env. Superintendent	EMPLOYER AEM	LOCATION CALLING FROM Meliadine	TELEPHONE 819-759-3555
M	ANY ALTERNATE CONTACT Sara Savoie	POSITION General Supervisor	EMPLOYER AEM	ALTERNATE CONTACT Meliadine LOCATION	ALTERNATE TELEPHONE 819-759-3555
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					