



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 2023-08-12		REPORT TIME 17:45		<input type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	OCCURRENCE DATE: MONTH – DAY – YEAR 2023-08-12		OCCURRENCE TIME 02:30			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01			WATER LICENCE NUMBER (IF APPLICABLE) 2AM-MEL 1631		
	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project				REGION <input type="checkbox"/> NWT <input type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 63 MINUTES 1 SECONDS 38			LONGITUDE DEGREES 92 MINUTES 13 SECONDS 6		
	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0			
G	ANY CONTRACTOR INVOLVED N/A		CONTRACTOR ADDRESS OR OFFICE LOCATION			
	PRODUCT SPILLED Tailings and Fresh Water		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 1500 L		U.N. NUMBER N/A	
H	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A		U.N. NUMBER N/A	
	SPILL SOURCE Paste Plant		SPILL CAUSE Human Error		AREA OF CONTAMINATION IN SQUARE METRES 15	
J	FACTORS AFFECTING SPILL OR RECOVERY N/A		DESCRIBE ANY ASSISTANCE REQUIRED N/A		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT N/A	
	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS A solid tailings hopper inside the Paste Plant overflowed onto the floor due to a faulty sensor. The plant operator hosed the floor down, causing approximately 1500 L of freshwater mixed with tailings to flow through an exterior door and onto the ground. The material was removed and placed at the Tailings Storage Facility (TSF). The coordinates of the spill are 63° 1'38.29"N 92°13'5.81"W. No water bodies were impacted by this spill. The closest water body (B7) is approximately 630 meters west. Pursuant to Part H, Item 8c of Water Licence 2AM-MEL1631, a follow up report will be issued after the investigation is completed. Reported by John Baechler, Environment Water Management Coordinator 819-759-3555 ext. 4603961 john.baechler@agnicoeagle.com, alternate contact: sara.savoie@agnicoeagle.com ext. 4603212.					
L	REPORTED TO SPILL LINE BY John Baechler	POSITION Env. W.M. Coordinator	EMPLOYER AEM	LOCATION CALLING FROM Meliadine	TELEPHONE 819-759-3555	
	ANY ALTERNATE CONTACT Sara Savoie	POSITION Env. Gen. Supervisor	EMPLOYER AEM	ALTERNATE CONTACT LOCATION Meliadine	ALTERNATE TELEPHONE 819-759-3555	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						