



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 06-06-2024		REPORT TIME 11:00		<input type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	OCCURRENCE DATE: MONTH – DAY – YEAR 06-06-2024		OCCURRENCE TIME 4:30			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01			WATER LICENCE NUMBER (IF APPLICABLE) 2AM-MEL1631		
	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 63 MINUTES 2 SECONDS 21			LONGITUDE DEGREES +2 MINUTES 13 SECONDS 41		
	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0			
G	ANY CONTRACTOR INVOLVED N/A		CONTRACTOR ADDRESS OR OFFICE LOCATION N/A			
	PRODUCT SPILLED Sewage		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 1.5 cubic meters		U.N. NUMBER N/A	
H	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A		U.N. NUMBER N/A	
	SPILL SOURCE Sewage Treatment Plant		SPILL CAUSE Overflow		AREA OF CONTAMINATION IN SQUARE METRES 12	
I	FACTORS AFFECTING SPILL OR RECOVERY None		DESCRIBE ANY ASSISTANCE REQUIRED None		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT None	
	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <p>Approximately 1.5m3 of sewage spilled onto the industrial pad at the Main Camp Sewage Treatment Plant. The spill was contained to the local area. Clean-up activities were immediately undertaken.</p> <p>The coordinates of the spill are 63°2'23" N 92°13'33.47" W. No water bodies were impacted by this spill. The nearest natural water body (Lake G2) is 360 m Northwest.</p> <p>Pursuant to Part H, Item 8c of water license 2AM-MEL1631, a follow-up report will be issued after the investigation is completed.</p> <p>Reported by Alexandre L. Bourassa, Environment Coordinator, 819-759-3555 ext. 4603996, alexandre.langlais-bourassa@agnicoeagle.com.</p>					
L	REPORTED TO SPILL LINE BY Alex L. Bourassa		POSITION Env. Coordinator	EMPLOYER AEM	LOCATION CALLING FROM Meliadine	TELEPHONE 819-759-3555
	ANY ALTERNATE CONTACT Randy Schwandt		POSITION Env. Coordinator	EMPLOYER AEM	ALTERNATE CONTACT LOCATION Meliadine	ALTERNATE TELEPHONE 819-759-3555
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY		POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME		CONTACT TIME	REMARKS	
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						