

**Dust Suppression**

**Photo 93** – Mine Haul Road Dust Suppression – July 2023



**Photo 94** – Mine Site Helicopter Pad Dust Suppression – July 2023



**Photo 95** – Aerial View of Mine Site Helicopter Pad with Dust Suppression Applied– September 2023




**Monitoring Programs**

**Photo 96** – Mine Site Surveillance Network Program Sampling – August 2023



**Photo 97** – Mine Site Surveillance Network Program Sampling – July 2023





**Photo 98** – Mine Site Aquatic Effects Monitoring Program Winter Lake Sampling – April 2023



**Photo 99** – Mine Site Aquatic Effects Monitoring Program Summer Lake Sampling – September 2023





**Photo 100** – Mine Site Core Receiving Effects Monitoring Program Sampling – September 2023



**Photo 101** – Mine Site Aquatic Effects Monitoring Program Stream Sampling – July 2023





**Photo 102** – Mine Site Aquatic Effects Monitoring Program Sampling – July 2023




**Photo 103** – Mine Site Core Receiving Effects Monitoring Program Sediment Sampling – September 2023






**Photo 104** – Mine Site Hydrology Monitoring– June 2023



**Photo 105** – Dustfall Sampling – June 2023



**Photo 106** – Dustfall Monitoring Site – April 2023



**Photo 107**– Height of Land Survey – October 2023





**Photo 108** – Groundwater Monitoring – September 2023



**Photo 109** – Mine Site Waste Rock Facility Surface Water Management Pond (MS-08) Sampling – August 2023



**Photo 110** – Air Quality Monitoring – March 2023



**Photo 111** – Garbage Clean Up – August 2023