
RAIL CV-16-2

LOCATION AND CROSSING DESCRIPTION

Site ID: CV-16-2 24-Jun-19 **Dates Surveyed:** Waterbody Type: Pond **Centreline UTM Coordinates:** 17W 514751 E 7965084 N **Project Interaction:** Pond Infilling Culvert Length (m): N/A **Number of Barrels:** N/A Culvert Diameter/Span (mm): Slope (%): N/A N/A

LOCATION





SUMMARY

This crossing is a dry low point on slightly elevated ground with well-established terrestrial vegetation no discrenable depressions or channels. There are small, shallow, isolated ponds to the north and northwest of the crossing and a larger pond (200 X 80 m) to the east that is also shallow and not connected to any other waterbody. The small pond 15 m to the north is to be infilled by the rail. The pond is small with a surface area of 400 m² and a shoreline length of 80 m. It is isolated, shallow (<0.5 m maximum depth) and does not provide fish habitat.

The surveyed UTM at CV-16-2 and the nearby pond infill are not fish habitat.

RAIL CV-16-2

24-JUN-19



A



 \mathbf{C}



В



D

Photos 1. Photos of crossing: (A) looking north along the rail centerline to the shallow isolated pond infill site; (B) looking east across the centerline with the larger pond in the background; (C) looking southeast along the centerline; and (D) looking west across the centerline.