



Quarry



APPENDIX D.3
PHOTO JOURNAL

**D.3.1 MARY RIVER MINE SITE PHOTO
SHEET**

ᓄᓗᓗᓐ ᓄᓗᓗᓐ ᓄᓗᓗᓐ ᓄᓗᓗᓐ ᓄᓗᓗᓐ ᓄᓗᓗᓐ



PHOTO 1 Mary River Mine Site Complex Aerial Layout □1 □ During 2014 Construction Program

ᐱᓂᓂᓂᓂ 1 ᓄᓂᓂᓂ ᐅᓂᓂᓂᓂᓂᓂ ᐃᓂᓂᓂᓂᓂᓂ ᓂᓂᓂᓂ ᐱᓂᓂᓂᓂᓂᓂᓂᓂ ᓂᓂᓂᓂ
1 – ᐱᓂᓂᓂᓂᓂ 2014-ᓂ ᐃᓂᓂᓂᓂᓂᓂᓂ ᐱᓂᓂᓂᓂᓂᓂᓂᓂᓂ



PHOTO 2 Mary River Mine Site Complex Aerial Layout □2 □ During 2014 Construction Program

ᐱᓂᓂᓂᓂ 2 ᓄᓂᓂᓂ ᐅᓂᓂᓂᓂᓂᓂ ᐃᓂᓂᓂᓂᓂᓂ ᓂᓂᓂᓂ ᐱᓂᓂᓂᓂᓂᓂᓂᓂᓂ ᓂᓂᓂᓂ
2 – ᐱᓂᓂᓂᓂᓂ 2014-ᓂ ᐃᓂᓂᓂᓂᓂᓂᓂ ᐱᓂᓂᓂᓂᓂᓂᓂᓂᓂ



PHOTO 3 Mary River Mine Site Air Strip Construction
 ᐸᓗᓕᓂ ᐅᓕᓕᓂᐸᓕᐸᐸᐸ ᐸᓕᐸᓕ ᓴᐸᓕᐸᓕᐸᓕ



PHOTO 4 Mary River Mine Site Air Strip Construction Completed
 ᐸᓗᓕᓂ ᐅᓕᓕᓂᐸᓕᐸᐸᐸ ᐸᓕᐸᓕ ᓴᐸᓕᓂᓕ ᐱᓕᓕᓕᐸᓕᐸᓕ



PHOTO 5 Mary River Mine Site Water Jetty
ᐅᓕᓕᓐᓂ ᐅᓕᓕᓐᓂᐅᓕᓐᓂ ᐅᓕᓐᓂ ᐅᓕᓐᓂᐅᓕᓐᓂ



PHOTO 6 Mary River Mine Site Water Jetty
ᐅᓕᓕᓐᓂ ᐅᓕᓕᓐᓂᐅᓕᓐᓂ ᐅᓕᓐᓂ ᐅᓕᓐᓂᐅᓕᓐᓂ



PHOTO 1 Aerial View - Steel Tank Bulk Fuel Storage Facility and infrastructure
laydown June 2014

[illegible]

PHOTO 2

Aerial View □ Milne Port Infrastructure Layout September 2014
ᐅᓄᔭᑦ ᐱᕈᑦ - ᐃᖋᐸᑦᑐᒻᗴᐳᑦ ᑐᓂᑲᑦᏰᕐᓵ ᓄᑍᑦᑦ ᐘᑐᖋᑯᑲᑦᑎᑦ
ᐘᑐᑲᑥᐁᑍᑦᐘᑦᑐᑦᑲᑦ ᐊᖋᑆᖋᑲᑬᑫᓶᓪᓷ ᑲᑎᐸᐸ 2014



PHOTO 3 Aerial View □ Ore Dock Construction June 2014
 ᐱᐃᐃᐃᐃᐃ 3 ᐃᐃᐃᐃ ᐃᐃᐃᐃ – ᐃᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃ
 ᐃᐃᐃᐃᐃᐃᐃ ᐃᐃ 2014



PHOTO 4 Aerial View □ Ore Dock Construction August 2014
 ᐱᐃᐃᐃᐃᐃ 4 ᐃᐃᐃᐃ ᐃᐃᐃᐃ – ᐃᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃ
 ᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃ 2014



PHOTO 5 Aerial View ☐ Ore Dock Construction September 2014
 የቅጽ 5 ምስል - ኦሪ ድክ ልማት ስራ ሰኔ 2014



PHOTO 6 Ore Pad September 2014
 ብረት 6 ነፍሰት ልማት ሰጠለ 2014



PHOTO 7 Settling Pond 1 (West pond) Construction
ᐅᓂᔭᑦ ᐃᕈᒪᐱᖁᑎᓄᗇ ᐊᓚᓴᐸᓯᓰᓄᗛ ᐆᓵᐳᓴᓴᓄᗛ
(ᐱᕋᓴᓴᓄᗛ ᐆᓵᐳᓴᓴᓄᗛ) ካᓚᓲᓶᑏᓴᓴ



PHOTO 8 Settling Pond 1 (West pond) Aerial View
 ᐱᓂᕈᑦᑐᑦ 8 ᐃᓂᕈᑦᑐᑦᐅᐸᐃᐃᐅᓯᕐᑐᓂᕐ ᑕᓯᐸᓯᕈᑦᑐᑦ 1
 (ᐱᓂᕈᑦᑐᑦ ᑕᓯᐸᓯᕈᑦᑐᑦ) ᓴᑦᑖᓂᑦ ᑕᑦᑖᑦᑐᑦ



PHOTO 9 Settling Pond 2 (East pond) Construction
ᐅᓄᑦᕈᑦ ᐱᓂᓃᑦᕈᑦ 2 (ᔭᒃᕆ ᐱᓂᓃᑦᕈᑦ) ᐸᓚᐸᓇᕐᑐᑦ
(ᔭᒃᕆ ᐱᓂᓃᑦᕈᑦ) ᓴᓗᕐᕋᐸᓇᕐᑐᑦ



PHOTO 10 Settling Pond 2 (East pond) Aerial View
ᐸᑦᓴᕈᖅ 10 ᐃᔪᒃᓱᓄᑦᐸᔭᐳᓂᓯᓵᑐᑦ ᐸᑦᓴᕈᖅ 2
 (ᐆᕋᕋᑦᐸ ᐸᑦᓴᕈᖅ) ᓫᑦᑦᑦ ᐸᑦᓴᕈᖅ



PHOTO 11 Landfarm □ earthworks complete
 ԳՆՔՅՈՒՄ 11 Ծածկո՞ւ - ծածու՞յթօն Անձ՚հԵՃՇՏՍ



PHOTO 12 Landfarm □ installation of Liner



PHOTO 13 Landfarm □ Contaminated Snow Cell - Liner ballasted in place with sand bags ready for seam sealing

[illegible]

PHOTO 14 Landfarm □ Placing Liner Cover Fill

[illegible]



PHOTO 15 Aerial View □ Conveyor Construction and Bladder Farm
Decommissioning August 2014

[illegible]

PHOTO 16 Aerial View □ Conveyor Construction □ Bladder Farm
Decommissioning Complete September 2014

[illegible]



PHOTO 17 Conveyor Construction Early November 2014

[illegible]

PHOTO 18 Drivehouse Construction November 2014

[illegible]



PHOTO 19 Conveyor Tower Moving November 2014

ᐅᓂᕈᓗᕐᑎᐱᖅ 19 ᐅᓂᕈᓗᕐᑎᐱᖅ ᐅᓂᕈᓗᕐᑎᐱᖅ ᐅᓂᕈᓗᕐᑎᐱᖅ
ᐅᓂᕈᓗᕐᑎᐱᖅ 2014



PHOTO 20 Conveyor Construction December 2014

[illegible]



PHOTO 1 Aerial View of Steensby Port exploration camp May 2014 □ Camp was not occupied in 2014

ᐱᐃᐃᐃᐃᐃᐃ 1 ᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃ 2014 – ᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃᐃᐃ 2014-ᐃ



PHOTO 2 Aerial View of Steensby Port exploration camp September 2014 □ Camp was not occupied in 2014

ᐱᐃᐃᐃᐃᐃᐃ 2 ᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃ 2014 – ᐃᐃᐃᐃᐃᐃ ᐃᐃᐃᐃᐃᐃᐃᐃᐃᐃᐃ 2014-ᐃ



PHOTO 1 Aerial View Mid-Rail Camp Close-Out □ Camp was not occupied in 2014

[illegible]

PHOTO 2 Aerial View Mid-Rail Camp Close-Out □ Camp was not occupied in 2014

[illegible]



PHOTO 1 Drilling operations at Milne Port (on ice) January 2014
 ᐅᐅᓂᐅᓂᓂ ᐱᓕᓕᐅᓂᓂ ᓂᐅᓂᐅᓂ ᐅᐅᐅᐅᐅᐅᐅ
 ᓂᐅᓂ ᐅᐅᓂᓂ ᐅᐅᐅᐅᐅᐅᐅ (ᓂᐅᐅ) ᓂᐅᐅᐅ 2014



PHOTO 2 Post-Drilling operations at Milne Port (on ice) January 2014
 ᐅᐅᐅᐅᐅᐅᐅ ᐅᐅᐅᐅᐅᐅ ᐱᓕᐅᐅᐅᐅ ᐅᓂᐅᐅᐅᐅ ᐅᐅᐅᐅᐅᐅᐅ
 ᓂᐅᓂ ᐅᐅᓂᓂ ᐅᐅᐅᐅᐅᐅᐅ (ᓂᐅᐅ) ᓂᐅᐅᐅ 2014



PHOTO 3 Waste Rock Stockpile drilling operations at Mary River July 2014

ᐅᓕᓐᓂᓐ 3 ᐅᓕᓐ ᐃᐃᓕᓕᓕᓕᓐᓂᓐᓂᓐ ᐅᓕᓐᓂᓐ ᐱᓕᓕᓐᓂᓐ ᐃᓕᓕᓐᓂᓐ
ᓕᓕᓐ 2014



PHOTO 4 Waste Rock Stockpile Post-drilling operations at Mary River July 2014

24 of 32



PHOTO 3 Completed bridge at km 17

ᐃᓴᓂᕈᓪᐅᑦ 3

ለኢትዮጵያ ፌዴራላዊ ዲሞክራሲያዊ ሪፐብሊክ 17 ዓ.ም. 1994 ዓ.ም. የሰነድ ምዝገባ ስር



PHOTO 4 Completed bridge at km 17 during Freshet

4

[illegible]

**D.3.7 Milne Port Bulk Fuel Transfer Photo
Sheet**

Δ⁶ΛΡ⁵Ϯ⁴ϥ³ϥ² Ϯ¹ϥ⁰Δ⁵Δ⁴Δ³Δ²Δ¹Δ⁰
Δ⁵Δ⁴Δ³Δ²Δ¹Δ⁰ Δ⁵Δ⁴Δ³Δ²Δ¹Δ⁰
Δ⁵Δ⁴Δ³Δ²Δ¹Δ⁰



PHOTO 1 Bulk Fuel Tanker in Milne Inlet September 2014
 41444444 1 44444444 44444444 44444444 44444444
 44444444 4444 44444444 44444444 2014



PHOTO 2 Bulk fuel tanker anchored outside Milne Port September 2014
 44444444 2 44444444 44444444 44444444 44444444 44444444
 44444444 44444444 44444444 44444444 44444444 44444444 2014



PHOTO 3 Bulk Fuel Transfer Personnel preparing to start the transfer at Milne Port September 2014

[illegible]

PHOTO 4 Deploying a containment boom during the Marine Spill Response Training August 2014

[illegible]



PHOTO 5 Marine Spill Response Training at Milne Port August 2014

ᐅᓂᕈᓗᕐᑦ 5 ᑕᓄᓂᕐ ᐃᓚᓂ ᐃᔨᕐᑭᓂᓂᕐᑦ ᐱᑕᓄᓂᕐ ᐊᑦᕈᓂᓂᕐᑭᓂᕐᑭᓂᕐ ᕐᐃᕐᑐᓂᕐᑐᓂᕐ
ᐃᐱᐅᑕᑦᐅᕐ ᕐᔨᕐᑐ ᐃᒪᕐᓴᓂᕐ ᑐᑕᑕᕐᔨᕐᓴᓂᕐ ᐊᓂᕐ 2014

[illegible][illegible]

ᐃᓕᓴᑦᑭᓄᑦ 3 ᑲᑎᒪᑎርᐅᓪᓗᑎᑲ ᐱᑲᐃᓐᓇᓖᓂᓪᓵᑦ ᓄᓇᓕᓐᓂ ᐅᓖᑲᐅᓶᓯᐅᓖᑲᑎᑦ
 ᐱᓕᓚᓖᑲᑎᓯᓂᑦ ᒥᓖᑎᒪᓕᓕᓐᓯ

[illegible]