

APPENDIX D.2

Tote Road Photo Sheet



PHOTO 1 – Dust Suppression Water Truck on Tote Road – August 2019



PHOTO 2 – Dust Suppression Calcium Truck on Tote Road – August 2019



PHOTO 3 – 740 Tire Drag for Dust Suppression – September 2019



PHOTO 4 –Tote Road Culvert CV-078 – July 2019



PHOTO 5 – Completed Construction on Culvert CV-111 – February 2019



PHOTO 6 – KM97 Bridge Crossing – August 2019



PHOTO 7 – KM63 Bridge Crossing – July 2019



PHOTO 8 – KM17 Bridge Crossing – July 2019



PHOTO 9 – L2 Laydown Active Migratory Bird Nest Survey – May 2019




PHOTO 10 – Routine Tote Road Water Quality Monitoring CV-112– June 2019



PHOTO 11 – Routine Tote Road Water Quality Monitoring CV-129 – June 2019



PHOTO 12 – OHT Crossing Tote Road at BG-32 – July 2019



PHOTO 13 – Snow Bank Height Survey – April 2019