

APPENDIX D

PHOTO JOURNAL

APPENDIX D.1

MINE SITE PHOTO SHEET



Photo 1 – Aerial View of Deposit No. 1 (Nuluujaak Pit) – September 2021



Photo 2 – Deposit No. 1 (Nuluujaak Pit) – July 2021



Photo 3 – Aerial View of Deposit No. 1 (Nuluujaak Pit) and Construction of By-Pass Road – October 2021



Photo 4 – Aerial View of ROM Stockpile Facility at KM106 – July 2021



Photo 5 – Aerial View of Waste Rock Facility (WRF) Water Treatment Plant (WTP) – July 2021



Photo 6 – Aerial View of Waste Rock Facility (WRF) and WRF Pond – September 2021



Photo 7 – Aerial View of Waste Rock Facility (WRF) – September 2021



Photo 8 – Aerial View of Waste Rock Facility (WRF) Pond (MS-08) – July 2021



Photo 9 – Waste Rock Facility (WRF) Expansion – April 2021



Photo 10 – Aerial View of Waste Rock Facility (WRF) Expansion and KM110.5 Laydown – September 2021



Photo 11 – New Maintenance Shop Construction at KM110.5 Laydown – November 2021



Photo 12 – Construction of New KM105 Surface Water Management Pond – October 2021



Photo 13 – Construction of New KM105 Surface Water Management Pond – September 2021



Photo 14 – Construction of New KM105 Surface Water Management Pond – December 2021



Photo 15 – Construction of New KM105 Surface Water Management Pond – October 2021



Photo 16 – Aerial View of Crusher Facility – August 2021



Photo 17 – Crusher Facility Surge Bin Shrouding – April 2021



Photo 18 – Crusher Facility Conveyor Shrouding – August 2021



Photo 19– Crusher Facility Conveyor Shrouding – March 2021



Photo 20 - Crusher Facility (CF) Pond (MS-06) – September 2021



Photo 21 – Aerial View of Maintenance Shops – May 2021



Photo 22 – Heavy Duty Shop Foundation Expansion – September 2021



Photo 23 – Aerial View of Mine Site Complex (MSC) – July 2021



Photo 24 – Aerial View of Mine Site Tank Farm (MS-03B)– September 2021



Photo 25 – Aerial view of Emulsion Plant – September 2021



Photo 26 – Aerial view of Mine Site Landfill – July 2021




Photo 27 – Aerial View of Mine Site Landfill, New Landfarm and Emulsion Plant – October 2021



Photo 28 – Construction of New Mine Site Landfarm (MS-05) – October 2021



Photo 29 – Construction of New Mine Site Warehouse Kitting Building – November 2021



Photo 30 – Mine Site Helicopter Pad Expansion – June 2021



Photo 31 – Mine Site Borrow Pit Remediation – September 2021



Photo 32 – Sailiivik Camp Complex – July 2021



Photo 33 – Aerial View of Mine Site Quarry (QRM2) – September 2021



Photo 34 – Freshet Preparations on Camp lake Jetty Road – May 2021



Photo 35 – Aerial View of Mine Site Camp Lake Settling Ponds – July 2021



Photo 36 – Aerial View of Mary River Airstrip – July 2021



Photo 37 – Aerial View of Mine Site Weatherhaven Camp – May 2021



Photo 38 – Aerial View of Mine Site Polishing Waste Stabilization Ponds (PWSPs) – July 2021



Photo 39 – Mine Site Road Dust Suppression – July 2021



Photo 40 – Mine Site Haul Road Dust Suppression – July 2021



Photo 41 – Mine Site Surveillance Network Program (SNP) Monitoring at MS-C-H – June 2021



Photo 42 – Mine Site SNP Monitoring at MQ-C-A – July 2021



Photo 43 – Mine Site Aquatic Effects Monitoring Program (AEMP) Winter Lake Sampling – April 2021



Photo 44 – Mine Site AEMP Sediment Sampling – September 2021



Photo 45 – Mine Site AEMP Summer Streams Sampling at MRY-REF2 – July 2021



Photo 46 – Mine Site Hydrology Program at H02– July 2021



Photo 47 – New Dustfall Site (DF-RN-03-S) – September 2021



Photo 48 – Active Migratory Bird Nest Survey (AMBNS) at Mine Site – July 2021



Photo 49 – New wildlife Camera Installed at Mine Site – August 2021



Photo 50 – Mine Site HTO Cabin – August 2021



Photo 51 – Minnow Gill Netting Program – August 2021



Photo 52 – Mine Site Walking Trail – July 2021



Photo 53 – Mine Site Walking Trail – July 2021