

APPENDIX D.2

TOTE ROAD PHOTO SHEET



Photo 1 – Aerial View of Open Burn Laydown at KM98 – September 2021



Photo 2 – Aerial View of KM97 Bridge Crossing – September 2021



Photo 3 – Aerial View of KM97 Laydown – September 2021



Photo 4 – Snowmobile Crossing Sign at KM90 – August 2021



Photo 5 – Aerial View of KM80 Laydown, Bridge and OHT Travelling North – September 2021



Photo 6 – KM80 Bridge Crossing – August 2021



Photo 7 – Aerial View of KM63 Bridge Crossing – September 2021



Photo 8 – KM63 Bridge Crossing – August 2021



Photo 9 – KM63 Ice Crossing Decommissioning – May 2021



Photo 10 – Aerial of OHT Parked at KM60 Rest Stop – September 2021



Photo 11 – Aerial View of KM17 Bridge Crossing – September 2021



Photo 12 – Dust Suppression Water Withdrawal Limit Signage and Housing for Water Truck Log at CV-128 – September 2021



Photo 13 – KM15 Borrow Pit Remediation – November 2021



Photo 14 – Aerial View of Open Burn Laydown at KM6 – August 2021



Photo 15 – Dust Suppression Water Truck on Tote Road – August 2021



Photo 16 – Dust Suppression Water Truck on Tote Road – August 2021



Photo 17 – Road Stabilization after DustBlok® Application



Photo 18 – 740 Tire Drag – August 2021



Photo 19 – Grader Maintaining Tote Road Surface – August 2021



Photo 20 – Loaded OHT Travelling North – August 2021



Photo 21– Tote Road Culvert CV-078 – June 2021



Photo 22– Tote Road Culvert BG-17 – September 2021



Photo 23 – Fish Habitat Assessment at Tote Road Culvert BG-32 – July 2021



Photo 24 – Fish Monitoring at Tote Road Culvert BG-01 – July 2021



Photo 25 – Routine Tote Road Water Quality Monitoring – August 2021



Photo 26 – Routine Tote Road Water Quality Monitoring – August 2021



Photo 27 – Tote Road KM76.5 Snow Stockpile – March 2021



Photo 28 – Snow Bank Height Survey – April 2021



Photo 29 – Lemming Tracks Observed during Snow Track Survey – March 2021



Photo 30 – Ptarmigan Tracks Observed at KM72.5 during Snow Track Survey – March 2021



Photo 31- Installation of New Dustfall Site DF-RS-03-S – September 2021



Photo 32 – New Dustfall Site (DF-RW-01) along Proposed Railway – August 2021



Photo 33– New Wildlife Cameras Installed at Dustfall Site DF-P-04 – August 2021



Photo 34 – Winter Dustfall Program – November 2021



Photo 35 – Silt Fence Installation at Snow Stockpile Site (TR-SN-03) – June 2021



Photo 36 –Height of Land Survey Conducted by Environmental Dynamics Inc. (EDI) – June 2021