

**Mobile Maintenance Buildings**



**Photo 37.** Mobile Maintenance Buildings - August

**Mine Site Complex (MSC)**



**Photo 38.** Mine Site Complex - August



**Tank Farms**



**Photo 39.** Mine Site Bulk Fuel Storage Facility (MS-03) for Vehicle and Equipment Re-fuelling- May



**Photo 40.** Bulk Fuel Storage Facility (MS-03) and Power Generation Facility - July





**Photo 41.** Mine Site Bulk Fuel Storage Facility (MS-03B) - August



**Photo 42.** Mine Site Bulk Fuel Storage Facility (MS-03B) - September



**Emulsion Plant**




**Photo 43.** Emulsion Plant - August

**Landfill and Landfarm**



**Photo 44.** Non-Hazardous Waste Landfill and Landfarm Facility - August





**Photo 45.** Soil Windrows in the Landfarm Facility Cell 1 - May



**Photo 46.** Landfarm Facility Cell 2 - July



**Sailliivik Camp Complex**



**Photo 47.** Sailliivik Camp Complex - June

**OHT Laydown and Laydown 2**



**Photo 48.** OHT Laydown and Laydown 2 - August



**Quarry 2**



**Photo 49. Mine Site Quarry (QRM2) - August**

**Incinerator Facility and Site Services Laydown**



**Photo 50. Incinerator Facility and Laydown - August**





**Photo 51. Site Services Building and Laydown - August**

#### **Warehouse and Flight Operations**



**Photo 52. Warehouse Building and Laydown - August**





**Photo 53.** Airstrip and Flight Operations - August

#### **Camp Lake**



**Photo 54.** Camp Lake Jetty Domestic Water Intake and Rip Rap Settling Ponds - August



**Weatherhaven Complex**



**Photo 55.** Weatherhaven Complex and Hazardous Waste Berms - August



**Photo 56.** Polishing Waste Stabilization Ponds - June



**Environmental Monitoring**

**Aquatic Effects Monitoring Program (AEMP)**



**Photo 57.** AEMP Water Sample Collection on Camp Lake - April



**Photo 58.** AEMP Water Sample Collection at Remote Site MRY-REF2 - June





**Photo 59.** AEMP Retrieving Sediment Sample from Sheardown Lake - July



**Photo 60.** AEMP Water Sample Collection on Camp Lake - August



**Hydrology Monitoring Program**



**Photo 61.** Hydrology Rhodamine Water Flow Survey - July



**Photo 62.** Hydrology Water Level Survey - August



**Surveillance Network Program (SNP)**



**Photo 63.** SNP Measuring Stream Depth and Velocity - May



**Photo 64.** SNP Water Sample Collection - July



### Ground Water Monitoring



**Photo 65.** Ground Water Field Parameter Monitoring - September

### Wildlife Monitoring



**Photo 66.** Height of Land Wildlife Survey - June





**Photo 67.** Lone Caribou Monitored While Walking in Stream near the Tote Road - June



**Photo 68.** Active Migratory Bird Nest Survey - July



**Remote Dust Monitoring**



**Photo 69.** NRCan Passive Dust Monitoring Filter Installation at Remote Site - June



**Photo 70.** Remote Site Dustfall Monitoring - August



**Snow Survey**



**Photo 80.** Snow Core Sample Collection East of Deposit 1 - May



**Photo 81.** Snow Core Sample Collection - May



**Freshet Preparation and Surface Water Management**



**Photo 82.** Snow Stockpile Inspection - March



**Photo 83.** Snow Removal to Expose Site Drainage Features Prior to Freshet - April





**Photo 84.** Loading Out Snow During exposure of Site Drainage Features Prior to Freshet - April



**Photo 85.** Maintaining ESC Silt Fence – April





**Photo 86.** Installing ESC Spring Berm at the Camp Lake Settling Ponds – June

#### **Dust Suppression**



**Photo 87.** Applying Water to Site Roadways as Dust Suppression – June