

APPENDIX D.3

Milne Port Photo Journal

Milne Port Site – Facility Infrastructure



Photo 1. Milne Port Waterfront, Ship loader, Ore Stockpile Pad – June



Photo 2. Milne Port Ore Stockpile Pad and Facility Infrastructure – August



Photo 3. West Ore Stockpile Pad, Surface Water Management Pond (MP-06) – June



Photo 4. Northwest cell of Ore Stockpile Pad, Surface Water Management Pond (MP-06) – June



Photo 5. East Ore Stockpile Pad, Surface Water Management Pond (MP-05) – August



Photo 6. East Ore Stockpile Pad, Surface Water Management Pond (MP-05) – June



Photo 7. Polishing Waste Stabilization Pond (MP-01A) and Main Generators – June



Photo 8. Steel Tank Bulk Fuel Storage Facility (MP-03) – August



Photo 9. Freight Dock and Sealift Ramp — August



Photo 10. Milne Port Accommodation, 380 Person Camp – July



Photo 11. Milne Port Accommodation, Port Site Complex (PSC) – August



Photo 12. Landfarm (MP-04) and Bermed Snow Dump (MP-04A) – August



Photo 13. Gate closed at Landfarm (MP-04) – August



Photo 14. Chain Link Fence Closed at Entrance to Hazardous Waste Berms 3 & 4 - August



Photo 15. Quarry (Q1) footprint – July



Photo 16. Quarry (Q1) Stockpiles and Facilities – July



Photo 17. L2 and R3 Laydowns south of Milne Port, along Tote Road – July



Photo 18. Bulk Fuel Tanker in Milne Inlet – September

Shiploading and Sea Lift



Photo 19. Tugboats Positioning Ore Carrier Golden Erling at the Ship Loading Dock— August



Photo 20. Ore Carrier Nordic Odyssey docked at the Ship Loader – August



Photo 21. Ore carrier Nordic Siku Docked at the Ship Loader – August



Photo 22. Sealift Carrier Claude A. Desgagnes Off-loading Supply Seacans– August



Photo 23. The Ice Breakers Botnica and Fennica in Milne Port – October

Environmental Monitoring Programs
Surveillance Network Program (SNP)



Photo 24. Routine Hydrology Monitoring at SNP Site (MP-C-K) – June



Photo 25. Routine Hydrology Monitoring at SNP site (MP-C-J) – June



Photo 26. Routine Hydrology Monitoring at SNP site, Quarry 1 (MP-Q1-01) – August

Water Treatment Monitoring



Photo 27. Pond Discharge Monitoring at (MP-05) – August



Photo 28. Routine Water Sampling at (MP-06) – October

Air Quality Monitoring



Photo 29. Passive Dustfall Monitoring Station (DF-P-04) – October



Photo 30. Passive Dustfall Monitoring Station (DF-RS-07) – December



Photo 31. Beta Attenuation Monitor (BAM 1020) Unit Inside Port Site Complex (PSC) – December

Dust Suppression



Photo 32. Dust Suppression Being Applied to the Ore Pad Stockpile – January



Photo 33. Dust Suppression Being Applied to the Ore Pad stockpile – May



Photo 34. 740 Water Truck Applying Water as Dust Supressant on the Tote Road – June

Snow Sampling Monitoring Program (SSMP)



Photo 35. Snow Sample Collection at (DF-P-08) – April

Marine Environmental Effects Monitoring Program (MEEP)



Photo 36. MEEMP Research Vessel Moored in Milne Inlet – August



Photo 37. Collecting Benthic Invertebrate Samples during MEEMP – September

Department of Fisheries and Oceans Canada (DFO) - Ballast Water Sampling Program (BWSP)



Photo 38. DFO Personnel Completing BWSP on an Ore Carrier in Milne Port – October



Photo 39. DFO Personnel Completing BWSP on an Ore Carrier in Milne Port – October

OPEP Training Course



Photo 40. Oil Pollution Emergency Plan (OPEP) Spill Response Training Exercise – July



Photo 41. Oil Pollution Emergency Plan (OPEP) Spill Response Training Exercise – July

Hunters and Trappers Organization (HTO)



Photo 42. Milne Inlet HTO Cabin– August

Milne Port Walking Trail



Photo 43. Walking Trail View Point– August