



Photo taken looking north at the covered contaminated granular from the bulk fuel storage facility undergoing decommissioning.



Photo taken from atop the south west corner of the New Sewage Effluent Pond looking north east.



Photo taken looking into the sump at the north east corner of the Landfarm.



Photo taken from atop the dyke looking into the contaminated snow containment.



Photo taken looking at the quarry face in the quarry showing the well developed benches and cover removed from atop solid rock.

PHOTOS

Milne Inlet September Inspection



Site of recently decommissioned bulk fuel containment



Existing PWSP now empty and being decommissioned



Site of recently decommissioned barrel fuel containment.



Hazardous waste storage containing bladder of contaminated material.



Fuel tank farm containment



New effluent pond