



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Agnico Eagle Mines LTD.	Samuel Tapp
Licence No. / Expiry	Representative's Title
2AM-WTP1830/March 27, 2030	Environment Coordinator
Land Authorization No.	Land Authorization No.
66H/08-01 Quarries	66H/08-02 Haul Road
Date of Inspection	Inspector
March 21, 2023	RMO Kyle Amsel
Activities Inspected	
<input checked="" type="checkbox"/> Camp <input type="checkbox"/> Drilling <input checked="" type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage	
<input checked="" type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other:	

SECTION 1	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
<p>On March 21, 2023 Resource Management Officer Kyle Amsel (Inspector) of Crown-Indigenous Relations and Northern Affairs Canada, (CIRNAC) conducted an inspection of Water Licence 2AM-WTP1830 (Licence). The Licence is issued to Agnico Eagle Mines Limited (Licensee) for the use of Waters and deposit of Wastes in support of a mining undertaking (Undertaking).</p> <p>Accompanying the Inspector was Environment Coordinator Samuel Tapp. The aforementioned is here on referred to as Representative. Also accompanying the Inspector was Resource Management Officer Joseph Monteith.</p> <p>Preliminary Information</p> <p>The primary focus of this inspection is snow management in and around the area of operations, compliance with Part J of the License, and any newly constructed pieces of infrastructure.</p> <p>Observations</p> <p>The following observations were made during the Inspection:</p> <ol style="list-style-type: none">Whale Tale Landfarm (Photos 1 & 2):<ol style="list-style-type: none">The Whale Tale Landfarm was recently commissioned.The facility has not been heavily used until inspection date.A sign is not present stating this is a waste disposal facility as required under Part B Item 10 of the Licence.The Berms of the facility appear well compacted with appropriate slopes. No liner was observed to be exposed in the facility.No other water management related concerns.Nemo Lake Water intake facilities ST-WT-05<ol style="list-style-type: none">At the time of the inspection there was no signage on the facilities as required under Part B Item 10 of the Licence. (Photo 3) On March 27, 2023 Representative emailed a photo of satisfactory temporary signage installed at Nemo Lake (Photo 4).The water flow meter at the time of inspection at Nemo Lake read 50L/min.Water usage from Nemo Lake at ST-WT-05 at the time of inspection was 19,507.2m³Un-used equipment/items subject to progressive abandonment and reclamation under Part J of the Licence:<ol style="list-style-type: none">Photo 5, A marine shipping container structure. Representative is un-aware of the current use of the structure, nor what it was used for in the past.Photo 6, Incinerator building. Representative states the incinerator has not been used since 2018.Photo 7, Burned out marine shipping container. No apparent use.Snow Management<ol style="list-style-type: none">No snow management issues were noted during the inspection.			
SECTION 2	<input type="checkbox"/> Comments (s. __)	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2)	<input type="checkbox"/> Action Required (s. __)
No incidents of non-compliance were observed.			
SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s.3)
<ul style="list-style-type: none">The Licensee shall present a plan to the Inspector by July 1, 2023 for the items listed in Section 1 Item 3, which demonstrates the following:<ul style="list-style-type: none">A demonstrated use or reuse of the items noted, orA plan with contingencies for the removal, dismantling, sale, or demolition with expected completion date.			

Licensee or Representative	Inspector's Name
Samuel Tapp	RMO Kyle Amsel
Signature	Signature
Date	Date
April 11, 2023	April 11, 2023

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---



PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
March 21, 2023	2AM-MEA1530	Samsung SM-G973W	RMO K Amsel
Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)		
Photo 1	Not available		



Description:
Newly commissioned landfarm facilities

Photo No.	Lat/Long (DD.MM.SS.SS, NAD83)
Photo 2	Not available



Description:
Newly commissioned landfarm facilities



Photo No.
Photo 3

Lat/Long (DD.MM.SS.SS, NAD83)
Not available



Description:
Water intake facilities at Nemo Lake. ST-WT-05.

Photo No.
Photo 4

Lat/Long (DD.MM.SS.SS, NAD83)
Not available



Description:
Temporary signage at Nemo Lake water intake.



Photo No.
Photo 5

Lat/Long (DD.MM.SS.SS, NAD83)
Not available



Description:
Unknown use marine shipping container structure.

Photo No.
Photo 6

Lat/Long (DD.MM.SS.SS, NAD83)
Not available



Description:
Incinerator building.



Photo No.
Photo 7

Lat/Long (DD.MM.SS.SS, NAD83)
Not available



Description:
Burned marine shipping container and other debris.