Water Licence Inspection Report

☒Original
☐Follow-Up Report

Authorization	Representative
2AM-WTP1830	**Robin Allard**
Authorization No. / Expiry	**Representative's Title**
March 27, 2030	**General Supervisor Environment**
Inspection Date	**Inspector**
May 28, 2026	**RMO Kyle Amsel**
Other Authorization/s	
Activities Inspected	
☐**Municipal** ☒ **Camp, Commercial** ☐ **Drilling** ☒ **Mining** ☒ **Construction** ☒ **Reclamation** ☒ **Fuel Storage** ☒ **Roads/Hauling** ☐ **Winter Hauling** ☐ **Camp, Private** ☐ **Other** Click or tap here to enter text.	

Section 1 Comments

On May 28, 2026 Resource Management Officer Kyle Amsel (Inspector) for Crown-Indigenous Relations and Northern Affairs Canada conducted an Inspection of Water Licence 2AM-WTP1830 (Licence) issued to Agnico Eagle Mines Ltd. (Proponent) for use of water and deposit of waste in support of a Mining Undertaking (Undertaking).

Accompanying the Inspector was Robin Allard General Supervisor Environment and Rowan Woodall Environmental Supervisor.

Preliminary Information

The purpose of the inspection was to determine compliance with the Licence in relation to freshet.

Observations

1) At the time of Inspection water usage at 36,135m^3 at Nemo Lake water intake ST-WT-5. (Photo 1) Sign for water intake facility were down during inspection. They have been returned prior to the writing of this report and there are no concerns from the Inspector. (Photo 2)
2) Waste water/contact water management
   a) Discharge into Whale Tale Lake at ST-WT-24 from the Whale Tale attenuation pond was ongoing at a rate of 200-175m^3/hour.
   b) Any excess water is being pumped to the IVR attenuation pond. (Photo 3)
   c) Groundwater Storage Pond (GSP) water us re-circulated for underground use (Photo 4)
3) IVR Diversion (Photo 5) No concerns noted.
4) Waste Rock Storage Facility sumps ST-WT-30 to 33 were not pumping at time of Inspection
5) ST-WT-3 Whale Tale Waste Rock Storage Facility contact water dyke, (Photo 6) no concerns from Inspector.
6) Whale Tale South Channel ST-WT-13 (Photo 7) no concerns from Inspector.
7) Mammoth (Kangislulik) Dyke (Photo 8).
8) Whale Tale Pit (Photo 9).


Section 2 Non-Compliance

No instances of non-compliance

Section 3 Action Required

No actions required

Section 4 Other

Licensee or Representative	Inspector's Name
Robin Allard	RMO Amsel
Signature	**Signature**
	
Date	**Date**
2026-08-19	July 22, 2026

Office Use Only: Follow-up report to be issued by Inspector ☐ Yes ☒ No

PHOTO LOG			
Date:	**Authorization Number:**	**Camera/Model:**	**Inspector**
May 28, 2026	2AM-WTP1830	Nikon Coolpix	RMO AMSEL

Photo #	**1**	**Coordinates:**	NA



Description:

Water Intake at Nemo Lake

Photo #	2	**Coordinates:**	NA



Description:

Fresh Water Intake sign at Nemo Lake water intake.

Photo #	3	Coordinates:	N65^0 24’ 26” W96^0 40’ 39”



Description:

IVR Attenuation Pond

Photo #	4	Coordinates:	N65^0 24’ 32” W96^0 41’ 9”



Description:

GSP 1

Photo #	5	Coordinates:	N65^0 24’ 52” W96^0 40’ 24”



Description:

IVR Diversion

Photo #	6	Coordinates:	N65^0 24’ 57” W96^0 41’ 42”



Description:

Whale Tale Waste Rock Storage Facility Dyke

Photo #	7	Coordinates:	N65^0 24’ 19” W96^0 43’ 27”



Description:

Whale Tale South Channel

Photo #	8	Coordinates:	N65^0 23’ 53” W96^0 40’ 45”



Description:

Mammoth Lake (Kangislulik) Dyke.

Photo #	9	Coordinates:	N65^0 24’ 12” 96^0 41’ 33”



Description:

Whale Tale Pit