



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 03-31-2019		REPORT TIME 18:45		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	OCCURRENCE DATE: MONTH – DAY – YEAR 03-31-2019		OCCURRENCE TIME 18:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-WTP-1826		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 51			LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED DIESEL		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 50 LITERS		U.N. NUMBER 1202	
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER	
I	SPILL SOURCE PUMP FEED LINE		SPILL CAUSE BUSTED LINE		AREA OF CONTAMINATION IN SQUARE METRES 20 M2	
J	FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <p>During dewatering operations at Whale Tail North, a fitting on the feed line of the dewatering pump, located on the pad, failed causing diesel fuel to spill on the ground.</p> <p>The pump was stopped and the spill contained rapidly with pads and snow. The area will be scraped clean and all contaminated material will be brought to the landfarm area.</p> <p>There were no off site impacts or discharge to any receiving watercourses. Distance to the closest lake is estimated at 100 meters towards the north portion of Whale Tail Lake.</p> <p>Spill location : Northing: 65'24'09" Easting: 96'41'13" on IOL. Contact information : Robin Allard 819-759-3555 ext. 4606838</p>					
L	REPORTED TO SPILL LINE BY Robin Allard	POSITION General Supervisor	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 8197593555	
M	ANY ALTERNATE CONTACT Nancy D-Harvey	POSITION Superintendent	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT MEADOWBANK LOCATION	ALTERNATE TELEPHONE 8677934610	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						