



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 2019-08-22	REPORT TIME 19:45	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 2019-08-21	OCCURRENCE TIME 22:30			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)	WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-WTP-1826			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION WHALE TAIL PIT PROJECT	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES 65 MINUTES 24 SECONDS 10	LONGITUDE DEGREES 96 MINUTES 42 SECONDS 43			
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE XOX OAO			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED HYDRAULIC OIL	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 200 LITERS	U.N. NUMBER NA		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE BACKHOE	SPILL CAUSE Hydraulic system failure	AREA OF CONTAMINATION IN SQUARE METRES 20 M2		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS During operations at Whale Tail Pit, the hydraulic system hose of BAC10 busted due to mechanical failure for a second time during the day. The equipment was shutdown and the contaminated material was picked up and brought to the appropriate area. There were no off site impacts or discharge to any receiving watercourses. Distance to the closest lake is estimated at 150 meters outside of Quarry 2. Spill location: Northing 65° 24' 14.7" Easting 96° 42' 33.2" on IOL Contact information: Nicolas Saucier 819 759 3555 ext. 4606759				
L	REPORTED TO SPILL LINE BY Nicolas Saucier	POSITION ENV. Sr Technician	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 819-759-3555
M	ANY ALTERNATE CONTACT Robin Allard	POSITION General Supervisor	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT LOCATION MEADOWBANK	ALTERNATE TELEPHONE 867-793-4610
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					