NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE
TEL: (867) 920-8130
FAX: (867) 873-6924
EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR **2019-10-26**	REPORT TIME **14:00**	☒ ORIGINAL SPILL REPORT, OR ☐ UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER ____-_____
B	OCCURRENCE DATE: MONTH – DAY – YEAR **2019-10-25**	OCCURRENCE TIME **17:00**		
C	LAND USE PERMIT NUMBER (IF APPLICABLE)	WATER LICENCE NUMBER (IF APPLICABLE) **NWB-2AM-WTP-1826**		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION **WHALE TAIL PIT PROJECT**	REGION ☐ NWT ☒ NUNAVUT ☐ ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES **65** MINUTES **01** SECONDS **51**	LONGITUDE DEGREES **96** MINUTES **09** SECONDS **21**		
F	RESPONSIBLE PARTY OR VESSEL NAME **AGNICO EAGLE MINES LTD**	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION **BAKER LAKE X0C 0A0**		
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION		
H	PRODUCT SPILLED **HYDRAULIC OIL**	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES **200L**	U.N. NUMBER **N/A**	
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER	
I	SPILL SOURCE **BAC08**	SPILL CAUSE **DAMAGED HYDRAULIC HOSE**	AREA OF CONTAMINATION IN SQUARE METRES	
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	

K ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS

During operations at Whale Tail pit, the operator struck the hydraulic cylinder against a rock, damaging the steel hydraulic line and causing hydraulic oil to spill on the ground. The equipment was shut down and maintenance was called to fix the line. The contaminated material was picked up and brought to the Meadowbank landfarm. Approximately 4m3 of contaminated material was collected.
There were no off site impacts or discharge to any receiving watercourses. Distance to the closest water body is 500m to Quarry 1.
Spill Location: Northing: 65' 24'11" Easting: 96' 42'14.8"
Contact Information: Tom Thomson 819 759 3555 ext. 4606744

L	REPORTED TO SPILL LINE BY **Tom Thomson**	POSITION **Env. Coordinator**	EMPLOYER **Agnico Eagle Mines**	LOCATION CALLING FROM **Meadowbank**	TELEPHONE **819 759 3555**
M	ANY ALTERNATE CONTACT **Robin Allard**	POSITION **Env. Gen. Supervisor**	EMPLOYER **Agnico Eagle Mines**	ALTERNATE CONTACT LOCATION **Meadowbank**	ALTERNATE TELEPHONE **819 860 1414**

REPORT LINE USE ONLY

N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130

LEAD AGENCY ☐ EC ☐ CCG ☐ GNWT ☐ GN ☐ ILA ☐ INAC ☐ NEB ☐ TC | SIGNIFICANCE ☐ MINOR ☐ MAJOR ☐ UNKNOWN | FILE STATUS ☐ OPEN ☐ CLOSED

AGENCY	CONTACT NAME	CONTACT TIME	REMARKS
LEAD AGENCY			
FIRST SUPPORT AGENCY			
SECOND SUPPORT AGENCY			
THIRD SUPPORT AGENCY			