



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 11-08-2022		REPORT TIME 14:30		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	B	OCCURRENCE DATE: MONTH – DAY – YEAR 11-07-2022		OCCURRENCE TIME 14:00		
C		LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER (IF APPLICABLE) 2AM-WTP-1830	
	D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION WHALE TAIL PROJECT			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E		LATITUDE DEGREES 65 MINUTES 01 SECONDS 51			LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21	
	F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0C 0A0 PO.540		
G		ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION		
	H	PRODUCT SPILLED HYDRAULIC OIL		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 220L		U.N. NUMBER
I		SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER
	J	SPILL SOURCE HAUL TRUCK		SPILL CAUSE EQUIPMENT FAILURE		AREA OF CONTAMINATION IN SQUARE METRES 10m2
K		FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT
	L	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS				
M		<p>During operations at the Whale Tail Project, the drive shaft failed on a haul truck causing a total of 220L of hydraulic oil to spill on to the ground at the bottom of Phase 1 in the Whale Tail Pit. The equipment was immediately shut off by the operator and mechanic called to have the equipment fixed. Approximately 4 m3 of contaminated materials has been collected and will be brought to the Meadowbank landfarm.</p> <p>Spill Location: Northing: N 65°24'12.07" W 96°42'19.26" on IOL</p> <p>There were no off-site impacts or discharges. Distance to the closest water body is 775m to Mammoth Lake</p> <p>Contact Information: Rowan Woodall, Environmental Lead Technician, 819-759-3555 Ext.:460-6808</p>				
	N	REPORTED TO SPILL LINE BY Rowan Woodall	POSITION Env. Lead Technician	EMPLOYER Agnico Eagle Mines	LOCATION CALLING FROM Meadowbank	TELEPHONE Ext.:460-6808
ANY ALTERNATE CONTACT Eric Haley		POSITION Env. Gen. Supervisor	EMPLOYER Agnico Eagle Mines	ALTERNATE CONTACT Meadowbank	ALTERNATE TELEPHONE 819-651-1010	
REPORT LINE USE ONLY						
O	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC		SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						