



Canada

## NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR <b>08-07-2023</b>	REPORT TIME <b>16:00</b>	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR <b>08-07-2023</b>	OCCURRENCE TIME <b>1:00</b>			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)	WATER LICENCE NUMBER (IF APPLICABLE) <b>2AM-WTP-1830</b>			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION <b>WHALE TAIL MINE</b>	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES <b>65</b> MINUTES <b>01</b> SECONDS <b>51</b>	LONGITUDE DEGREES <b>96</b> MINUTES <b>09</b> SECONDS <b>21</b>			
F	RESPONSIBLE PARTY OR VESSEL NAME <b>AGNICO EAGLE MINES LTD</b>	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>BAKER LAKE X0C 0A0 PO.540</b>			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED <b>HYDRAULIC OIL</b>	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>600L</b>	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE <b>HAUL TRUCK</b>	SPILL CAUSE <b>DAMAGED EQUIPMENT</b>	AREA OF CONTAMINATION IN SQUARE METRES <b>15m2</b>		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <b>During the operations at the Whale Tail Mine, the haul truck's hydraulic system was damaged when it accidentally made contact with a rock while maneuvering into position for unloading. This incident led to the spillage of approximately 600 liters of hydraulic fluid onto the ground of the Whale Tail Rock Storage Facility. The operator quickly shut off the equipment, and the mechanic team was immediately called to assess the situation. The contaminated material will be collected and transported to the Whale Tail Landfarm. Spill Location: N 65°24'26.12"N 96°44'10.43"on IOL There were no off-site impacts or discharges. Distance to the closest water body is 385 m to Mammoth Lake Contact information: Samuel Tapp 819-759-3555 EXT.: 460-6744</b>				
L	REPORTED TO SPILL LINE BY <b>Samuel Tapp</b>	POSITION <b>Env. Coordinator</b>	EMPLOYER <b>Agnico Eagle Mines</b>	LOCATION CALLING FROM <b>Meadowbank</b>	TELEPHONE <b>819-759-3555</b>
M	ANY ALTERNATE CONTACT <b>Robin Allard</b>	POSITION <b>Env. Gen. Supervisor</b>	EMPLOYER <b>Agnico Eagle Mines</b>	ALTERNATE CONTACT <b>Meadowbank</b> LOCATION	ALTERNATE TELEPHONE <b>819-860-1414</b>
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					