



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 11-21-2023		REPORT TIME 9:50		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____	
B	OCCURRENCE DATE: MONTH – DAY – YEAR 11-20-2023		OCCURRENCE TIME 20:00					
C	LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER (IF APPLICABLE) 2AM-WTP-1830				
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION WHALE TAIL MINE				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 51			LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21				
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0C 0A0 PO.540					
G	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION					
H	PRODUCT SPILLED DIESEL FUEL		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 300L		U.N. NUMBER 1202			
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER			
I	SPILL SOURCE FUEL LINE		SPILL CAUSE HUMAN ERROR		AREA OF CONTAMINATION IN SQUARE METRES 80m2			
J	FACTORS AFFECTING SPILL OR RECOVERY Buried Cables		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT			
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS During the refueling process at Whale Tail Mine, an operator forgot to remove the fuel nozzle from their equipment prior departing the underground fuel farm. The damage to the fuel line resulted in ~300L of diesel fuel to spill within pump shack and onto the ground within the lined area of the fuel farm. Once noticed the emergency spill kit was deployed. The contaminated material will be collected and brought to the Whale Tail landfarm and contaminated absorbent material will be collected and disposed of at the Hazmat. Spill Location: N 65°24'25.54" W96°40'52.82" on IOL There were no off-site impacts or discharges. Distance to the closest water body is 1000m to Whale Tail South Lake Contact information: Rowan Woodall 819-759-3555 EXT.: 460-6744							
L	REPORTED TO SPILL LINE BY Rowan Woodall		POSITION Env. Coordinator		EMPLOYER Agnico Eagle Mines		LOCATION CALLING FROM Meadowbank	
							TELEPHONE 819-759-3555	
M	ANY ALTERNATE CONTACT Robin Allard		POSITION Env. Gen. Supervisor		EMPLOYER Agnico Eagle Mines		ALTERNATE CONTACT Meadowbank	
							ALTERNATE TELEPHONE 819-860-1414	
REPORT LINE USE ONLY								
N	RECEIVED AT SPILL LINE BY		POSITION STATION OPERATOR		EMPLOYER		LOCATION CALLED YELLOWKNIFE, NT	
							REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC					SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
AGENCY		CONTACT NAME			CONTACT TIME		REMARKS	
LEAD AGENCY								
FIRST SUPPORT AGENCY								
SECOND SUPPORT AGENCY								
THIRD SUPPORT AGENCY								